

Our Ref: mp220016

Your Ref: RA6457356

Date: 23/08/2022

FAO The Court
C/o Montreal Prestige Ltd
Rose Hill Works
Ground Floor
Nelson Street
BL3 2RW

REPAIRABLE REPORT


Dear Sirs


RE: Road traffic Accident: Nadeem Chaudhry: 16/08/2022

In accordance with your instructions received on 17/08/2022 requesting us to provide an independent accident damage report, we assessed the damage on 19/08/2022. Vehicle located at Rose Hill Works, Nelson Street, Bolton, Lancashire, BL32RW. Our findings are as detailed below:

Make	SKODA	Registration	MA13XML
Model	OCTAVIA SE PLUS TDI	Status	Repair
Category		Salvage Value	
Repair Cost	£1,830.89	Legal Status	Roadworthy
Engineer Value	£3,000.00	Impact Magnitude	Light to Moderate

Impact Area





Our Ref: mp220016

Your Ref: RA6457356

Date: 23/08/2022

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the rear.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £1,850.00 would be reasonable on this occasion.

Vehicle Data

Retail Value	£3,000.00
Trade Value	£1,050.00
Engineer's Value	£3,000.00
Glass's Code	TX87
VIN	TMBBG7NE0D0020286
Odometer	262224
Engine	1598
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	

Main new parts required


Rear Bumper Lining
Left Rear Bumper Side Bracket
Left Rear Bumper Side Support Plate
Rear Bumper Repair Kit
Rear Bumper Lining Screw
Right Reflector

Rear Bumper Reinforcement
Right Rear Bumper Side Bracket
Right Rear Bumper Side Support Plate
Rear Bumper Spoiler
Left Reflector

Additional operations

Rear bumper protection trim
System Diagnostic Check (Post Repair)
Car Care Kit
Environmental Charge
Paint Rear Bumper k/e
Paint Colour mixing (1)

Repair Method Research Allowance
System Diagnostic Check (Pre Repair)
De-Nib/Polish
Wash/Clean
Paint Prep. synthetics (on vehicle without pre-painting)
Paint Sample colour creation (1)




Our Ref: mp220016

Your Ref: RA6457356

Date: 23/08/2022

Repair Cost Calculations

Hours	5.30
Hourly Rate	£62.50
Total Labour	£331.25
Parts	£596.53
Paint/Materials	£462.96
Specialist/Other	£135.00
Sub total	£1,525.74
Vat	£305.15
Total Estimated Cost	£1,830.89



Our Ref: mp220016

Your Ref: RA6457356

Date: 23/08/2022

Statement of Truth

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.

I understand that proceedings for contempt of court may be brought against anyone who makes, or causes to be made, a false statement in a document verified by a statement of truth without an honest belief in its truth.

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: mp220016

Your Ref: RA6457356

Date: 23/08/2022

FAO The Court
C/o Montreal Prestige Ltd
Rose Hill Works
Ground Floor
Nelson Street
BL3 2RW

Fee Note

MA13XML.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £150.00

Sub Total: £150.00

VAT: £30.00

Total Due: £180.00

Payment

Please make cheques payable to Collision Engineers and quote reference mp220016.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o Montreal Prestige Ltd confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10