

Our Reference

26-1805416/2373541

Your Reference

MW/44454/1

Date

14th Apr 2026

LAIRD

Total Loss Damage Assessment Report

F.A.O. The Court
Qdos Accident Assistance Ltd
St Ann's House Parsonage Green
Wilmslow
Cheshire
SK91HG

Dear Sirs


In accordance with your written instructions asking us to provide an accident damage report, we have considered the supplied documentation and our findings are detailed below:

Vehicle Details

Make	Vauxhall
Model	Vivaro 2900 Cdti
Registration	DY17UVA
Engineer's Value	£11,894.00
Salvage Value	£1,665.16
Salvage Category	Category S
Status	Total Loss
Legal Status	Unroadworthy
Impact Magnitude	Moderate

Claim Details

Claimant	Mr Stephen Paterson
Accident Date	02/04/2026
Instruction Date	07/04/2026

Impact Diagram

Our Reference

26-1805416/2373541

Your Reference

MW/44454/1

Date

14th Apr 2026

LAIRD

Total Loss Damage Assessment Report

Vehicle Information

Retail Value	£11,894.00	Trade Value	£6,103.00
Engineers Value	£11,894.00	Gearbox	Manual
Valuation Source	Glass's	Body Type	Panel Van
Driven Axle	Front	VIN	WOLF7G60XHV644186
Colour	White	Registration Date	12/07/2017
Vehicle Width	2283	Engine	1.6
Vehicle Length	5398	Fuel	Diesel
Euro NCAP Rating	6	Condition	Good
Odometer	87117 Miles Extrapolated from recent MOT		

Unroadworthy Comments

Rear Panel Damage - Structure Has become compromised

Loose Insecure and Sharp Components

Our Reference

26-1805416/2373541

Your Reference

MW/44454/1

Date

14th Apr 2026

LAIRD

Total Loss Damage Assessment Report

Vehicle Comments

Condition Alerts	Not Checked	Finance	No finance agreement recorded
Mileage	No mileage discrepancies	Write Off	No write-off recorded
Stolen	No stolen record	Plate Change	No issues recorded.
Color Changes	No issues recorded.	Origin and Use	No issues recorded.
Keepers	No issues recorded.	MOT History	No issues recorded.
Tax and Sorn	No issues recorded.	At Risk	No risk marker recorded

New Parts Required

Front Bumper	Front Air Int Grille	Air Inlet Bracket
L/f Bumper Cover	Frt Bumper Trim Set	L/f Bumper Bracket
R/f Bumper Bracket	Front Bumper Bracket	L/rad-grille Bracket
R/rad-grille Bracket	Front Grille Bracket	Frt Impact Damper
Frt Lwr Bumper Cover	Grille	Left Headlamp Assy
Rr Ctr Bumper	L/r Bumper	L/r Bumper Bracket
Rear Bumper Support	Rear Number Plate	L/lower W-door Hinge
L/r Loading Door	L/r Lamp	L/r Lower Lamp
L/r Reflector	No Plate Lamp Trim	End Panel

Our Reference

26-1805416/2373541

Your Reference

MW/44454/1

Date

14th Apr 2026

LAIRD

Total Loss Damage Assessment Report

Additional Operations

Methods / Ads Id	Bsi 10125
Epa Charge	Aries Charge
Car Care Kit	4 Wheel + Adj

Repair Costs Calculations

Hours	35.10
Hourly Rate	£83.28
Total Labour	£2,923.13
Parts	£3,787.27
Paints / Materials	£994.28
Specialist / Other Items	£468.43
Sub Total	£8,173.11
VAT	£1,634.62
Total Estimated Cost	£9,807.73

Our Reference

26-1805416/2373541

Your Reference

MW/44454/1

Date


14th Apr 2026

LAIRD


Total Loss Damage Assessment Report

Repair Costs Analysis

Repair Cost Breakdown



Pre-Accident Value -v- Total Repair Cost



Our Reference

26-1805416/2373541

Your Reference

MW/44454/1

Date

14th Apr 2026

LAIRD

Total Loss Damage Assessment Report

Repair Summary

Having examined the damage as presented, we have estimated repair times and methods, which are detailed below. We would recommend the vehicle to be dealt with on a total loss basis. The damage sustained to the vehicle would render the salvage as category 'S' (structural total loss) in accordance with the Salvage Code Of Practice.

We are not aware of any outstanding recovery or storage charges.

We would suggest settlement be sought at a net figure of £10,228.84, being the pre-accident value, less the anticipated salvage value.

The [salvage](#) should be disposed of in accordance with the Code of Practice for the disposal of motor vehicle [salvage](#) produced by the ABI and the vehicle listed on [MIAFTR](#).

Alternatively, the vehicle can be returned to use if repaired to a safe and legal standard, and capable of passing a MOT test thereafter.

As the inspected vehicle is unroadworthy or undriveable and considered beyond economical repair, in order to prevent any issues with safety, legislation, insurance or DVLA, we suggest it should be moved to safe storage.

The salvage has been reviewed by an AQP

Data

We have used [Glass's](#) and [Cazana](#) guides and adverts from sites such as AutoTrader to assist with the valuation of the vehicle and have assumed the mileage reading displayed on the odometer is accurate and the vehicle has its appropriate documentation such as service history & MOT test certificate where applicable.

In order to mitigate losses we have carried out a basic inspection dealing with the vehicle's damaged area; we are happy to accept further instructions to confirm the identity, condition or roadworthiness of the remainder of the vehicle.

Automated / AI systems may be utilised for the extraction, transfer and structuring of data from source materials and third-party inputs. All matters of analysis, opinion and conclusion are the independent product of the appointed engineer, provided in accordance with their duty to the Court under CPR Part 35. No automated system has exercised judgement, discretion or influenced the opinions expressed within this report.

Our Reference

26-1805416/2373541

Your Reference

MW/44454/1

Date

14th Apr 2026

LAIRD

Total Loss Damage Assessment Report

>

Statement of Truth

I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

I understand that proceedings for contempt of court may be brought against anyone who makes, or causes to be made, a false statement in a document verified by a statement of truth without an honest belief in its truth.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



Mr Dawson CGL3 VDA CGL2 Salvage Categorisation CAE AMIMI
engineers@laird-assessors.com

Our Reference

26-1805416/2373541

Your Reference

MW/44454/1

Date

14th Apr 2026

LAIRD

Total Loss Damage Assessment Report

Qdos Accident Assistance Ltd
St Ann's House Parsonage Green
Wilmslow
Cheshire
SK91HG

Fee Note

Vehicle Registration	DY17UVA
Agreed Fee: Collate data, calculate estimate, research valuation. Produce Desktop Vehicle Damage Assessment Report	£100.00
Subtotal:	£100.00
V.A.T:	£20.00
Total Due:	£120.00

Payment Terms

BACS Payment to Barclays, Sort Code: 20-50-36, Account No: 00455660, Account Name: Laird Assessors Limited. You can also pay by card by calling 0151 342 0598. For all payments please quote reference number 26-1805416.

This is not a tax invoice - a receipted invoice will follow upon full payment. We will not accept any reduction to our fee through the Detailed Assessment process.

Any requests for addendum reports or letters, including those required for clarification, plus Counsel, Court or other meetings, will be subject to further charges & subject to Civil Procedure Rule 35.6.

Terms: As per our agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. In addition, for unpaid debts up to £999.99. We are allowed to claim compensation of £40.00.