

FAO The Court

REPAIRABLE REPORT

Dear Sirs


RE: Road traffic Accident: Mr Colin Russell: 30/04/2026


In accordance with your instructions received on 30/04/2026 requesting us to provide an independent accident damage report, we assessed the damage on 07/05/2026. Vehicle located at Image-based Assessment. Our findings are as detailed below:

Make	AUDI	Registration	BD70FCO
Model	A4 SPORT 35 TFSI MH	Status	Repair
Category		Salvage Value	
Repair Cost	£10,574.16	Legal Status	Unroadworthy
Engineer Value	£16,268.00	Impact Magnitude	Moderate



Impact Area





Our Ref: a.pch261139

Your Ref: 575461

Date: 07/05/2026

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand rear.

ENGINEER'S COMMENTS

Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the offside

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION


The vehicle is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £10,575.00 would be reasonable on this occasion.

Vehicle Data

Retail Value	£16,268.00
Trade Value	£14,804.00
Engineer's Value	£16,268.00
Glass's Code	
VIN	WAUZZZF41MA013686
Odometer	52820
Engine	1984
Fuel	Petrol
Extras	
Condition	Good



Our Ref: a.pch261139

Your Ref: 575461

Date: 07/05/2026

Main new parts required

R/R Door Insulation
R/R Door Hndl Rr Pad
Rear Bumper Spoiler
R/R Bumper Guide
Rr Bumper Clamp Kit
R/Ct/Rr Park Sens Sl
R/In/Rr Park Sens Sl
Cutting Filament
Cleaning Solution
Rear Spacer
Applicator
R/R Side Panel
R/S Window Bond Kit
Cleaning Solution
Applicator
R/R W-Arch Liner Mtg
R/R Tyre
Bead Sealer
Welding Materials

R/R Dr Hndl Frt Pad
Rear Cover Bumper
R/R Bumper Bracket
R/R Out Bumper Guide
L/Ct/Rr Park Sens Sl
L/In/Rr Park Sens Sl
Actuator
Rear Screen Bond Kit
Rear Screen Primer
Applicator
R/R Outer Lamp
R/R Air Grille
Cutting Filament
Applicator
R/R Wheelhouse Cvr
R/R Wheel Cover
R/R Tyre Valve
Boron Drills (8Mm)
Sundry Parts

Repairs required


R/R Outer Wheelhouse
Clamp & Pull

Test Weld

Additional operations

Check Water Test
Paint R/R Side Panel New Part Painting
Blend R/R Outer Wheelhousesurface Paint
Blend R/R Door Handle Trimsurface Paint Plast.
Blend R/Outer A-Pillar Surface Paint
Blend Rear Cover Surface Paint Plast.
Blend Upper Tailgate Surface Paint
Paint Denib / Polish Paint
Paint Additional Masking Bootlid
Assessment Fee
Vehicle Care Kit
Wheel Alignment
Corrosion Mat

Paint Two Coat Metallic
Paint Rear Cover Bumper New Part Paint K1r
Blend R/R Door Lower Surface Paint
Blend R/Lower Sill Trim Surface Paint Plast.
Blend R/Roof Member Surface Paint
Blend R/R End Panel Surface Paint
Blend Fuel Filler Flap Surface Paint Plast.
Blend Touch Up Bolts Surface Paint
Paint Preparation For Pre-Painting
Epa Charge
Paint Consumable
Alloy Wheel Refurb Specialist
Envir Sustainability Specialist



Our Ref: a.pch261139


Your Ref: 575461

Date: 07/05/2026

Repair Cost Calculations

Hours	41.70
Hourly Rate	£103.06
Total Labour	£4,297.60
Parts	£2,697.35
Paint/Materials	£1,241.39
Specialist/Other	£575.46
Sub total	£8,811.80
Vat	£1,762.36
Total Estimated Cost	£10,574.16






Our Ref: a.pch261139


Your Ref: 575461


Date: 07/05/2026















Our Ref: a.pch261139

Your Ref: 575461

Date: 07/05/2026






Our Ref: a.pch261139

Your Ref: 575461

Date: 07/05/2026






Our Ref: a.pch261139

Your Ref: 575461

Date: 07/05/2026







Our Ref: a.pch261139

Your Ref: 575461

Date: 07/05/2026









Our Ref: a.pch261139

Your Ref: 575461

Date: 07/05/2026





Our Ref: a.pch261139

Your Ref: 575461

Date: 07/05/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

N O'Reilly - ATA VDA

engineers@collisionengineers.co.uk



Our Ref: a.pch261139

Your Ref: 575461

Date: 07/05/2026

FAO The Court

Fee Note

BD70FCO.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £150.00

Sub Total: £150.00

VAT: £30.00

Total Due: £180.00

Payment

Please make cheques payable to Collision Engineers and quote reference a.pch261139.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10