

Our Reference26-
1755094/2285706**Your Reference**

SA75GZN

Date

27th Jan 2026



Total Loss Damage Assessment Report

F.A.O. The Court**C/o**

Dear Sirs

In accordance with your written instructions asking us to provide an accident damage report, we have considered the supplied documentation and our findings are detailed below:

Vehicle Details

Make	Audi
Model	Q4 E-tron Black Ed 45 Quattro
Registration	SA75GZN
Engineer's Value	£39,820.00
Salvage Value	£7,167.59
Salvage Category	Category S
Status	Total Loss
Legal Status	Unroadworthy
Impact Magnitude	Heavy

Key Details

Claimant	
Accident Date	21/01/2026
Instruction Date	27/01/2026

Impact Diagram

Our Reference

26-
1755094/2285706

Your Reference

SA75GZN

Date

27th Jan 2026



Total Loss Damage Assessment Report

Repair Summary

Having examined the damage as presented, we have estimated repair times and methods, which are detailed below. We would recommend the vehicle to be dealt with on a total loss basis. The damage sustained to the vehicle would render the [salvage](#) as category 'S' (structural total loss) in accordance with the [Salvage Code Of Practice](#).

We are not aware of any outstanding recovery or storage charges, but please confirm with the repairer.

We would suggest settlement be sought at a net figure of £34,706.65, being the pre-accident value, less the anticipated [salvage](#) value.

The [salvage](#) should be disposed of in accordance with the Code of Practice for the disposal of motor vehicle [salvage](#) produced by the ABI and the vehicle listed on [MIAFTR](#).

Alternatively, the vehicle can be returned to use if repaired to a safe and legal standard, and capable of passing a MOT test thereafter.

As the inspected vehicle is unroadworthy or undriveable and considered beyond economical repair, in order to prevent any issues with safety, legislation, insurance or DVLA, we suggest it should be moved to safe storage.

The salvage has been reviewed by an AQP

Data

We have used [Glass's](#) and [Percayso](#) guides and adverts from sites such as AutoTrader to assist with the valuation of the vehicle and have assumed the mileage reading displayed on the odometer is accurate and the vehicle has its appropriate documentation such as service history & M.o.T. test certificate where applicable.

In order to mitigate losses we have carried out a basic inspection dealing with the vehicle's damaged area; we are happy to accept further instructions to confirm the identity, condition or roadworthiness of the remainder of the vehicle.

We use AI to assist with the compilation of some aspects of this report.

Our Reference

26-
1755094/2285706

Your Reference

SA75GZN

Date

27th Jan 2026



Total Loss Damage Assessment Report

Statement of Truth

I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

I understand that proceedings for contempt of court may be brought against anyone who makes, or causes to be made, a false statement in a document verified by a statement of truth without an honest belief in its truth.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A handwritten signature in black ink that reads "K. Covill". The signature is written in a cursive, slightly stylized font.

Mr Covill IMI VDA, CAE, AMIMI
engineers@laird-assessors.com

Our Reference26-
1755094/2285706**Your Reference**

SA75GZN

Date

27th Jan 2026



Total Loss Damage Assessment Report

Vehicle Information

Retail Value	£39,820.00	Steering	To be checked
Trade Value	£36,785.00	Brakes	To be checked
Engineers Value	£39,820.00	Gearbox	Automatic
Glass's Code	Glass Guide	Body Type	Estate
Driven Axle	All - Permanent	VIN	WAUZZZFZ2SP071070
Colour	Grey	Registration Date	05/09/2025
Vehicle Width	2108	Vehicle Length	4588
Fuel	Electricity	Euro NCAP Rating	6
Condition	Good	Odometer	4000 Miles Extrapolated from recent MOT

Unroadworthy Comments

Extent of Damage

Our Reference26-
1755094/2285706**Your Reference**

SA75GZN

Date

27th Jan 2026



Total Loss Damage Assessment Report

New Parts Required

L/f Wing	L/wing Badge	L/r Wing Extens Frt
Left Front Door	L/f Upper Door Hinge	L/f Lower Door Hinge
L/f Door Check	L/f Outer Door Seal	L/f Window Regulator
L/f Out Channel Mldg	L/f Door Lower Cover	L/r Door
L/r Upper Door Hinge	L/r Lower Door Hinge	L/r Door Check
L/r Outer Door Seal	L/r Door Lower Cover	L/door Frame Seal
L/f Door Frame	L/f Sill Moulding	L/b-pillar Reinf
L/r Wing Extension	L/s Window Bond Kit	Cutting Filament
Cleaning Solution	Left Backrest Pad	Right Backrest Pad
L/f Backrest Cover	R/f Backrest Cover	L/f Side Airbag
R/f Side Airbag	L/f Side Airbag Sys	R/f Side Airbag Sys
L/f S/airbag Sensor	R/f S/airbag Sensor	L/head Airbag System
R/head Airbag System	L/head Airbag	R/head Airbag
L/r Airbag Sensor	R/r Airbag Sensor	Headlining
R/r Speed Sensor	Rear Support Frame	Rear Stabiliser
L/r Coupling Rod	R/r Wheel Hub/brg	R/r Shock Absorber
R/r Dr-shaft Screw	L/r Wheel Brg Hsg	R/r Wheel Brg Hsg
L/r Tie Rod	R/r Tie Rod	R/r Lwr Control Arm
F/l/lwr/rr Ctrl Arm	F/r/lwr/rr Ctrl Arm	L/r Upp Frt Cont Arm
L/r Upp Rr Cont Arm	R/r Upp Rr Cont Arm	L/r Wheel
R/r Wheel	L/r Tyre	R/r Tyre
Bead Sealer	Body Filler	Boron Drill 8mm

Our Reference

26-
1755094/2285706

Your Reference

SA75GZN

Date

27th Jan 2026



Total Loss Damage Assessment Report

Repairs Required

L/r Side Panel

Ev/hyb Shutdown

2nd Trial Fit

Adas Steer Angle

Our Reference26-
1755094/2285706**Your Reference**

SA75GZN

Date

27th Jan 2026



Total Loss Damage Assessment Report

Additional Operations

Epa Charge	Pre_rep_diag_check
Post_rep_diag_check	Veh Care Kit
Ev Full Charge	Uplift Tape
Sound Pad X 2	Welded Panels
Adas Calibration	4 Wheel Align -adj
Yard Charge	Jig Bracket Hire
Suspension Bolts	

Our Reference26-
1755094/2285706**Your Reference**

SA75GZN

Date

27th Jan 2026



Total Loss Damage Assessment Report

Repair Costs Calculations

Hours	94.4999026
Hourly Rate	£103.06
Total Labour	£9,739.16
Parts	£15,113.83
Paints / Materials	£1,935.05
Specialist / Other Items	£1,291.78
Sub Total	£28,079.82
VAT	£5,615.96
Total Estimated Cost	£33,695.78

Our Reference

26-
1755094/2285706

Your Reference

SA75GZN

Date


27th Jan 2026



Total Loss Damage Assessment Report

Repair Costs Analysis

Repair Cost Breakdown



Pre-Accident Value -v- Total Repair Cost

