

Our Ref: htu26014

Your Ref: RV17 ZDA

Date: 27/02/2026

FAO The Court
C/O HTU Assessors Ltd
The Old Courthouse
18-22 St Peters Churchyard
Derby
DE1 1NN

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Fadumo Abdirisag Abdullahi : 19/02/2026


In accordance with your instructions received on 25/02/2026 requesting us to provide an independent accident damage report, we assessed the damage on 26/02/2026. Vehicle located at ITV Solutions, Cotton Brook Road, Derby, Derbyshire, DE23 8YJ. Our findings are as detailed below:

Make	NISSAN	Registration	RV17ZDA
Model	QASHQAI N-VISION D	Status	T/Loss
Category	N	Salvage Value	£1,857.80
Repair Cost	£7,764.08	Legal Status	Unroadworthy
Engineer Value	£9,289.00	Impact Magnitude	Moderate



Impact Area





Our Ref: ht26014

Your Ref: RV17 ZDA

Date: 27/02/2026

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the left hand side.

ENGINEER'S COMMENTS

20% has been deducted from the pre accident valuation due to the vehicle being a previous total loss.

Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the nearside and impacted wheel and tyre.

VEHICLE HISTORY CHECK

According to the Experian database; Category S total loss claim Structural Damage See the Condition details An entry exists on the MIAFTR register to this effect dated 04/07/2022, loss dated 09/05/2022

PRE-INCIDENT CONDITION


The vehicle is considered to be in good condition for its age and type.

SETTLEMENT

We consider that an equitable settlement would be £7,431.20 which represents the pre-accident engineer value of the vehicle of £9,289.00 less the value of the salvage of £1,857.80.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £1,857.80. **We have not taken any action towards removal of the salvage at this time.**



Our Ref: htu26014

Your Ref: RV17 ZDA

Date: 27/02/2026

Vehicle Data

Retail Value	£11,612.00
Trade Value	£10,799.00
Engineer's Value	£9,289.00
Glass's Code	8THK
VIN	SJNFEAJ11UZ000895
Odometer	40052
Engine	1197
Fuel	Petrol
Extras	
Condition	Good
Unrelated Damage	


Main new parts required

Left Rear Door Shell
Left Rear Door Repair Kit
Left Side Panel W/arch Protective Moulding
Left Rear Door Trim Support Kit

Left Rear Door Protective Moulding
Left Rear Side Panel
Left Side Glass Repair/Bonding Kit
Left Rear Door Trim Clip

Repairs required

Rear Bumper Lining



Our Ref: htu26014

Your Ref: RV17 ZDA

Date: 27/02/2026


Additional operations

.Assessment Damage Appraisal Charge
.Pre repair cleaning charge
.Standard shutdown
.System Diagnostic Check (Post Repair)
.Vehicle Care Kit
Boron Drill
Corrosion Protection
Load / Unload vehicle to ramp
Polish
Second man lift
Paint Left A-Post, Upper
Paint Left Front Door Outer Handle
Paint Left Rear Door Outer Handle
Paint Rear Bumper k/d-e
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)
Sundries

.Environmental Charge
.QC & Road Test
.Sundries
.System Diagnostic Check (Pre Repair)
.Wash/Clean
Check sill for damage
Corrosion Protection additional panel
NSR tyre
Seam Sealant
Wheel Alignment (check)
Paint Left Front Door, Complete
Paint Left Rear Door, Complete
Paint Left Rear Side Panel, Complete
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)
Set-up time

Repair Cost Calculations

Hours	31.80
Hourly Rate	£83.28
Total Labour	£2,648.30
Parts	£2,119.22
Paint/Materials	£1,069.12
Specialist/Other	£633.43
Sub total	£6,470.07
Vat	£1,294.01
Total Estimated Cost	£7,764.08




Our Ref: htU26014

Your Ref: RV17 ZDA

Date: 27/02/2026






Our Ref: htu26014

Your Ref: RV17 ZDA

Date: 27/02/2026






Our Ref: htu26014

Your Ref: RV17 ZDA

Date: 27/02/2026






Our Ref: ht26014

Your Ref: RV17 ZDA

Date: 27/02/2026






Our Ref: ht26014

Your Ref: RV17 ZDA

Date: 27/02/2026






Our Ref: htu26014

Your Ref: RV17 ZDA

Date: 27/02/2026






Our Ref: htu26014

Your Ref: RV17 ZDA

Date: 27/02/2026






Our Ref: ht26014

Your Ref: RV17 ZDA

Date: 27/02/2026






Our Ref: ht26014

Your Ref: RV17 ZDA

Date: 27/02/2026





Our Ref: htu26014

Your Ref: RV17 ZDA

Date: 27/02/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.

We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - M.Inst.IAEA

engineers@collisionengineers.co.uk