

Date: 28/01/2025

FAO The Court
C/O Blackstone Legal
Unit 18, Gillington Road
Bradford
BD8 9NL

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Patel Prashant: 12/01/2025


In accordance with your instructions received on 25/01/2025 requesting us to provide an independent accident damage report, we assessed the damage on 28/01/2025. Vehicle located at Fosse Way, Syston, Leicester, Leicestershire, LE7 1NG. Our findings are as detailed below:

Make	BMW	Registration	YE55XGP
Model	320D SE AUTO	Status	T/Loss
Category	N	Salvage Value	£250.00
Repair Cost	£4,175.63	Legal Status	Unroadworthy
Engineer Value	£2,500.00	Impact Magnitude	Moderate



Impact Area





Our Ref: black25026

Your Ref: SA:25365SA

Date: 28/01/2025

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the front.

ENGINEER'S COMMENTS

28/01/2025 - Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the nearside front.

The valuation is based on market research.

14/2/2025 - UPDATED REPORT: - The vehicle owner has disputed our valuation and provided some market research as evidence to dispute the same. On review of this and through conducting our own, we feel the value is £2500.00

VEHICLE HISTORY CHECK

According to the Experian database; there is a plate change on record

PRE-INCIDENT CONDITION

The vehicle is considered to be in above average condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £2,250.00 which represents the pre-accident engineer value of the vehicle of £2,500.00 less the value of the salvage of £250.00.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £250.00. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	
Trade Value	
Engineer's Value	£2,500.00
Glass's Code	BBQH
VIN	WBAVC32020VA30955
Odometer	125926
Engine	1995
Fuel	Diesel
Extras	
Condition	Above Average
Unrelated Damage	



Our Ref: black25026

Your Ref: SA:25365SA

Date: 28/01/2025

Main new parts required

Front Bumper Lining
Left Front Bumper H/lamp Washer Jet Flap/Lid
Left Front Bumper Outer Distance-Sensor
Front Bumper Lining Clip
Front Bumper Lining Nut

Front Bumper Reinforcement
Front Bumper Repair kit
Front Bumper Distance-Sensor Glue Kit
Front Bumper Lining Screw
Bonnet Badge


Additional operations

Assessment Damage Appraisal Charge
Energy cost supplement
Older vehicle allowance
Repair method research charge
Sundries
System Diagnostic Check (Pre Repair)
Wash/Clean
Paint Left Headlamp Washer Flap/Guard
Paint Right Front Wing, Complete
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

De-nib/ polish
Environmental Charge
QC & Road Test
Standard shutdown
System Diagnostic Check (Post Repair)
Vehicle Care Kit
Paint Front Bumper
Paint Left Front Wing, Complete
Paint Bonnet
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

Repair Cost Calculations

Hours	13.10
Hourly Rate	£80.00
Total Labour	£1,048.00
Parts	£1,012.38
Paint/Materials	£987.63
Specialist/Other	£431.68
Sub total	£3,479.69
Vat	£695.94
Total Estimated Cost	£4,175.63



Our Ref: black25026


Your Ref: SA:25365SA


Date: 28/01/2025





Date: 28/01/2025





Our Ref: black25026

Your Ref: SA:25365SA

Date: 28/01/2025

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: black25026

Your Ref: SA:25365SA

Date: 28/01/2025

FAO The Court
C/O Blackstone Legal
Unit 18, Girdlington Road
Bradford
BD8 9NL

Fee Note

YE55XGP.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £180.00

Sub Total: £180.00

VAT: £36.00

Total Due: £216.00

Payment

Please make cheques payable to Collision Engineers and quote reference black25026.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/O Blackstone Legal confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10