

FAO The Court
C/O QC Law Solicitors
633 Halifax Road
Liversedge
WF15 8HG

REPAIRABLE REPORT

Dear Sirs


RE: Road traffic Accident: Mr Anthony Mohammed Cauchie: 13/04/2026


In accordance with your instructions received on 28/04/2026 requesting us to provide an independent accident damage report, we assessed the damage on 28/04/2026. Vehicle located at Cariocca Business Park, Hellidon Close, Manchester, M12 4AH. Our findings are as detailed below:

Make	VOLKSWAGEN	Registration	GM23KPZ
Model	GOLF LIFE TDI S-A	Status	Repair
Category		Salvage Value	
Repair Cost	£7,074.88	Legal Status	Unroadworthy
Engineer Value	£15,998.00	Impact Magnitude	Moderate to Heavy



Impact Area





Our Ref: qcl26150

Your Ref: 225849.TA

Date: 30/04/2026

NATURE OF INCIDENT

The vehicle has suffered moderate to heavy collision/impact damage to the left hand front.

ENGINEER'S COMMENTS

20% has been deducted from the pre accident valuation due to the vehicle being a previous total loss.

Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the front end, broken headlamp and insecure front bumper.

VEHICLE HISTORY CHECK

According to the Experian database; Category S total loss claim Structural Damage See the Condition details An entry exists on the MIAFTR register to this effect dated 08/01/2026, loss dated 18/12/2025

PRE-INCIDENT CONDITION


The vehicle is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £7,075.00 would be reasonable on this occasion.

Vehicle Data

Retail Value	£19,998.00
Trade Value	£16,598.00
Engineer's Value	£15,998.00
Glass's Code	
VIN	WVWZZZCD9PW037409
Odometer	20267
Engine	1968
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	



Our Ref: qcl26150
Your Ref: 225849.TA

Date: 30/04/2026

Main new parts required

Front Bumper Lining
 Left Front Bumper Trim, Side
 Front Bumper Repair kit
 Front Bumper Distance-Sensor Glue Kit
 Left Front Wing Liner, Front
 Front Grille Repair/Fastening Kit
 Bonnet
 Bonnet Insulation Repair/Fastening Kit
 Right Bonnet Hinge
 Bonnet Clip

Front Bumper Impact Absorber/Filler
 Left Front Bumper Plate Support
 Left Front Bumper Distance-Sensor
 Left LED Headlamp, Complete (with Indicator)
 Front Grille
 Front Grille Screw
 Bonnet Repair/Fastening Kit
 Left Bonnet Hinge
 Bonnet Hinge Kit


Additional operations

.Assessment Damage Appraisal Charge
 .Pre repair cleaning charge
 .Standard shutdown
 .System Diagnostic Check (Post Repair)
 .Vehicle Care Kit
 ADAS Calibration
 NSF tyre
 Wheel Alignment (check)
 Paint Left Front Bumper Distance-Sensor
 Paint Right Front Wing, Complete
 Paint Prep. metal (on vehicle without pre-painting)
 Paint Colour mixing (1)

.Environmental Charge
 .QC & Road Test
 .Sundries
 .System Diagnostic Check (Pre Repair)
 .Wash/Clean
 Load / Unload vehicle to ramp
 Second man lift
 Paint Front Bumper
 Paint Left Front Wing, Complete
 Paint Bonnet
 Paint Prep. synthetics (combined-operation work)
 Paint Sample colour creation (1)

Repair Cost Calculations

Hours	17.70
Hourly Rate	£83.28
Total Labour	£1,474.06
Parts	£2,314.95
Paint/Materials	£1,268.40
Specialist/Other	£838.32
Sub total	£5,895.73
Vat	£1,179.15
Total Estimated Cost	£7,074.88



























Our Ref: qcl26150

Your Ref: 225849.TA

Date: 30/04/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - M.Inst.IAEA

engineers@collisionengineers.co.uk



Our Ref: qcl26150

Your Ref: 225849.TA

Date: 30/04/2026

FAO The Court
C/O QC Law Solicitors
633 Halifax Road
Liversedge
WF15 8HG

Fee Note

GM23KPZ.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £200.00

Sub Total: £200.00

VAT: £40.00

Total Due: £240.00

Payment

Please make cheques payable to Collision Engineers and quote reference qcl26150.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/O QC Law Solicitors confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10