

Ageas
Fortis House
Tollgate
Eastleigh
SO53 3YA

17 June 2026

Our reference: 575689
Your reference: GDMPA00938241

Our client: Greendown Trust
Our vehicle: DK19ATU
Your Insured: Vanda Hartley
Policy number: GDMPA00938241
Your vehicle: YF63MYU
Incident date: 05/05/2026

We are now in a position to formally present our claim arising from the incident that occurred on **05/05/2026**, for which we hold your insured 100% responsible.

WITHOUT PREJUDICE SAVE AS TO COSTS, Please arrange payment of the following on the receipt of this letter

- Total repair costs: £3,815.58
- Engineer's fee: £180.00
- Total costs: £3,995.58

The **quickest and easiest method** of payment is by BACS to the following account:

- **Account Name:** Connexus Client PRM
- **Sort Code:** 20-50-90
- **Account Number:** 63901165

Should you prefer to deal through solicitors, please provide their full contact details by return.

This letter serves as sufficient notice in accordance with **Section 152 of the Road Traffic Act 1988**.

If you have any questions or require clarification, feel free to contact our claims team directly.

Yours sincerely,

Connexus Insurance Solutions

Connexus Insurance Solutions
1210 Centre Park Square
Warrington
WA1 1RU
Vat:GB764554994

Payment Term: Due on Receipt
Invoice Date : 10/06/2026
Invoice Reference: 575689

Client Details

Client Name: Greendown Trust
Make: Peugeot
Model: Boxer candrive easyon blu
Vehicle Registration: DK19ATU

Description	Value (£)
Labour	£ 1,549.01
Parts	£ 727.04
Paint & Materials	£ 509.28
Specialist Charges	£ 394.32
Net Total	£ 3,179.65
VAT at 20%	£ 635.93
Gross Total	£ 3,815.58

Our bank details:

Barclays Bank
Sort code: 20-50-90
Account: 63901165
Payee: Connexus Client PRM

FAO The Court

REPAIRABLE REPORT

Dear Sirs


RE: Road traffic Accident: Greendown Trust: 05/05/2026


In accordance with your instructions received on 13/05/2026 requesting us to provide an independent accident damage report, we assessed the damage on 21/05/2026. Vehicle located at Image-based Assessment. Our findings are as detailed below:

Make	PEUGEOT	Registration	DK19ATU
Model	BOXER CANDRIVE EAS	Status	Repair
Category		Salvage Value	
Repair Cost	£3,815.58	Legal Status	Unroadworthy
Engineer Value	£24,581.00	Impact Magnitude	Moderate



Impact Area





Our Ref: a.pch261241

Your Ref: 575689

Date: 21/05/2026

NATURE OF INCIDENT

The minibus has suffered moderate collision/impact damage to the right hand rear.

ENGINEER'S COMMENTS

Please note the minibus is unroadworthy due to the broken rear lamp.

VEHICLE HISTORY CHECK

We confirm having checked this minibus on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The minibus is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £3,825.00 would be reasonable on this occasion.

Vehicle Data

Retail Value	£24,581.00
Trade Value	£19,664.00
Engineer's Value	£24,581.00
Glass's Code	
VIN	VF3YE2MFC12K43239
Odometer	5669
Engine	1997
Fuel	Diesel
Extras	
Condition	Good

Main new parts required

R/R Bumper Corner
R/R Lamp
Sundry Parts

Rr Bumper Clamp Kit
R/S-Panel Rr Mldg

Repairs required

R/Upp Corner Pillar

R/R Lower Pillar

Additional operations

Check Miracle Pull Set Up
Blend R/R Lower Side Panelsurface Paint
Paint Additional Mask Quarter Glass
Assessment Fee
Vehicle Care Kit
Corrosion Mat
Delivery To Client Returning Veh

Paint R/Upp Corner Pillar Repair Painting <50%
Paint Denib / Polish Paint
Paint Preparation For Pre-Painting
Epa Charge
Paint Consumable Specialist
Panel Sundries P/P Specialist
Envir Sustainability Specialist

Repair Cost Calculations


Hours	18.60
Hourly Rate	£83.28
Total Labour	£1,549.01
Parts	£727.04
Paint/Materials	£509.28
Specialist/Other	£394.32
Sub total	£3,179.65
Vat	£635.93
Total Estimated Cost	£3,815.58











Our Ref: a.pch261241

Your Ref: 575689

Date: 21/05/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

N O'Reilly - ATA VDA AQP

engineers@collisionengineers.co.uk



Our Ref: a.pch261241

Your Ref: 575689

Date: 21/05/2026

FAO The Court

Fee Note

DK19ATU.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £150.00

Sub Total: £150.00

VAT: £30.00

Total Due: £180.00

Payment

Please make cheques payable to Collision Engineers and quote reference a.pch261241.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10

Satisfaction Note

Name: Greendown Trust

Address: 10 Allerton Hill
Chapel Allerton
Leeds

LS7 3QB

Registration Number: DK19ATU

Make: Peugeot

Model: Boxer candrive easyon blu

Claim Reference: 575689

Declaration:

This is to certify that the repairs carried out on the above vehicle have been completed, and the vehicle has been handed over to the undersigned.

I acknowledge that if, for any reason, my car stereo requires unlocking with a specific key or code, it is my responsibility to provide this information or obtain it from the manufacturer.

Signature: 

Print Name: Greendown Trust

Date: 12/06/2026

Connexus Insurance Solutions, 1210 Centre Park Square, Centre Park, Warrington, WA1 1RU
Tel: 0333 043 3797 **Fax:** 0333 043 3798 **Email:** enquiries@connexus.co.uk **Web:** www.connexusinsurancesolutions.co.uk

Registered in England and Wales No: 3499256 Registered Office: 1210 Centre Park Square, Centre Park, Warrington, WA1 1RU