Our Reference	Your Reference	Date
26-1953697/2609422	JF/48913/1	9th Oct 2026

Repairable Damage Assessment Report

F.A.O. The Court
Qdos Accident Assistance Ltd
St Ann's House Parsonage Green
Wilmslow
Cheshire
SK91HG

Dear Sirs
In accordance with your written instructions asking us to provide an accident damage report, we have considered the supplied documentation and our findings are detailed below:


Vehicle Details

Make	**Land Rover**
Model	**Defender Hdtp Xdyn Hse Dmhev A**
Registration	**AK24UYD**
Engineer's Value	**£53,388.00**
Repair Cost	**£32,125.67**
Status	**Repairable**
Legal Status	**Unroadworthy**
Impact Magnitude	**Heavy**

Claim Details

Claimant	**Serenity Pools**
Accident Date	**24/09/2026**
Instruction Date	**08/10/2026**

Impact Diagram



Repairable Damage Assessment Report

Vehicle Information

Retail Value	**£53,388.00**	Trade Value	**£49,343.00**
Engineers Value	**£53,388.00**	Gearbox	**Automatic**
Valuation Source	**Glass's**	Body Type	**Panel Van**
Driven Axle	**All - Permanent**	VIN	**SALEACAW4S2363604**
Colour	**Black**	Registration Date	**08/08/2024**
Vehicle Width	**1996**	Engine	**3**
Vehicle Length	**4583**	Fuel	**Diesel**
Euro NCAP Rating	**6**	Condition	**Fair**
Odometer	**23140 Miles Provided by the repairing garage**		

Unroadworthy Comments

Extent of Damage

New Parts Required

Rear Bumper	L/r Bumper Cover	L/bumper Bracket
L/blindspot Sensor	L/r Bumper Bracket	L/r Lwr Bumper Cover
Rr Bumper L/lwr Cvr	Rear Bumper Support	Towing Eye Reinf
Rr Ctr Bumper Brkt	Rear Bumper Reinf	L/screw M8x16

Repairable Damage Assessment Report

L/nut	Inner Rear End Panel	Outer Rear Panel
End Panel Reinf	Bootlid/tailgate	Boot/tailgate Seal
Rear Screen Seal	Rear Manufact Badge	Type Badge
Rear Screen Bond Kit	Spacer	L/r Lamp/fog Lamp
L/r Lamp	L/side Repeater Lamp	L/fastening Clip
L/screw M6x30	L/r Lamp Cover	L/r Lamp Trim
L/mounting Clip 12	L/r Stripe	L/r Side Panel
L/r Rearlamp Supp	L/r Rearlamp Supp	L/r W-arch Moulding
L/fastening Clip	L/air Vent Grille	L/r Wheelhouse Cover
L/screw M5 X 19	L/rivet	L/fastening Clip
L/nut	L/fastening Clip	L/fastening Clip
L/s Window Bond Kit	L/s Window Bond Kit	L/inn Side Panel Cpl
L/d-pillar Trim Brkt	L/r Roof Frame Reinf	Rr Exhaust Silencer
Silencer Shield	L/r Lower Rubber Brg	R/r Lower Rubber Brg
L/r Stabilizer Rod	R/r Stabilizer Rod	L/r Strg Knuckle
L/r Wheel Bearing	L/r Wheel Hub	L/r Nut
L/r Inf Press Sensor	L/r Upp Control Arm	L/r Axle Control Arm
L/r Lwr Control Arm	L/r Axle Arm Cover	L/r Support Arm Brkt
L/r Support Arm Brkt	L/raxle Link Rr Prot	L/r Wheel
Adhesive Set	X 20 Rivets/jlr	X 10 Rivets/jlr
X 40 Rivets/jlr	X 10 Rivets/jlr	X 25 Rivets/jlr
X 25 Rivets/jlr	X 25 Rivets/jlr	X 25 Rivets/jlr

Repairable Damage Assessment Report

X 10 Rivets/jlr	X 20 Rivets/jlr	X 50 Rivets/jlr
X 25 Rivets/jlr	X 25 Rivets/jlr	Spr Tip
Stone Chipping	Edge Sealer	Mud Flap Set
Rear Chequer Plate		

Repairs Required

Setup Repair System	Dress Welded Joints

Additional Operations

N/s/r Tyre	Adas Calibration
1x Wheel Balance	Battery Check
Methods / Ads Id	Bsi 10125
Epa Charge	Aries Charge
Car Care Kit	4 Wheel + Adj
Engineer Fee	

Repairable Damage Assessment Report


Repair Costs Calculations

Hours	88.5999831252109
Hourly Rate	£118.52
Total Labour	£10,500.87
Parts	£12,979.42
Paints / Materials	£2,224.90
Specialist / Other Items	£1,066.20
Sub Total	£26,771.39
VAT	£5,354.28
Total Estimated Cost	£32,125.67


Repairable Damage Assessment Report

Repair Costs Analysis

Repair Cost Breakdown



Pre-Accident Value -v- Total Repair Cost




Repairable Damage Assessment Report

Vehicle Images





Repairable Damage Assessment Report







Repairable Damage Assessment Report






Repairable Damage Assessment Report






Repairable Damage Assessment Report





Repairable Damage Assessment Report





Repairable Damage Assessment Report






Repairable Damage Assessment Report





Repairable Damage Assessment Report






Repairable Damage Assessment Report






Repairable Damage Assessment Report





Repairable Damage Assessment Report





Repairable Damage Assessment Report





Repairable Damage Assessment Report






Repairable Damage Assessment Report






Repairable Damage Assessment Report





Repairable Damage Assessment Report





Repairable Damage Assessment Report





Repairable Damage Assessment Report





Repairable Damage Assessment Report





Repairable Damage Assessment Report





Repairable Damage Assessment Report





Repairable Damage Assessment Report





Repairable Damage Assessment Report





Repairable Damage Assessment Report





Repairable Damage Assessment Report





Repairable Damage Assessment Report





Repairable Damage Assessment Report





Repairable Damage Assessment Report






Repairable Damage Assessment Report






Repairable Damage Assessment Report






Repairable Damage Assessment Report





Repairable Damage Assessment Report





Repairable Damage Assessment Report

Repair Summary

Having examined the damage as presented, we have estimated repair times and methods, which are detailed below. The repair cost total is currently estimated at £32,125.67, which is sufficiently lower than the pre-accident value to consider the vehicle economically, safely and physically repairable.

This figure is an estimate based on a visual examination only, so may increase slightly for minor additional items. We recommend the vehicle is stripped thoroughly to check for any latent damage prior to ordering parts, or commencing work. If any supplementary damage is found above minor sundry items, repairers can inform us via Audatex or supp@laird-assessors.com and wait for further written authority before continuing.

Any other queries relating to the content of this report should be directed to query@laird-assessors.com and may be subject to additional fees.

We are not aware of any outstanding recovery or storage charges.

We have agreed and authorised repairs with the repairing garage .

Repair Duration

We consider that repairs will take approximately 22 to 23 working days, assuming there are no restrictive issues, inter alia, parts & sub-contractor availability, workshop loading, authority, etc.

Data

We have used Glass's and Cazana guides and adverts from sites such as AutoTrader to assist with the valuation of the vehicle and have assumed the mileage reading displayed on the odometer is accurate and the vehicle has its appropriate documentation such as service history & MOT test certificate where applicable.

In order to mitigate losses we have carried out a basic inspection dealing with the vehicle's damaged area; we are happy to accept further instructions to confirm the identity, condition or roadworthiness of the remainder of the vehicle.

Repairable Damage Assessment Report

Automated / AI systems may be utilised for the extraction, transfer and structuring of data from source materials and third-party inputs. All matters of analysis, opinion and conclusion are the independent product of the appointed engineer, provided in accordance with their duty to the Court under CPR Part 35. No automated system has exercised judgement, discretion or influenced the opinions expressed within this report.

Statement of Truth

I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

I understand that proceedings for contempt of court may be brought against anyone who makes, or causes to be made, a false statement in a document verified by a statement of truth without an honest belief in its truth.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



Mr Raymond Dawson CGL3 VDA CGL2 Salvage Categorisation CAE AMIMI
engineers@laird-assessors.com

Our Reference	Your Reference	Date
26-1953697/2609422	JF/48913/1	9th Oct 2026

Repairable Damage Assessment Report

Qdos Accident Assistance Ltd
St Ann's House Parsonage Green
Wilmslow
Cheshire
SK91HG

Fee Note

Vehicle Registration	**AK24UYD**
Agreed Fee: Collate data, calculate estimate, research valuation. Produce Desktop Vehicle Damage Assessment Report	**£70.00**
Subtotal:	**£70.00**
V.A.T:	**£14.00**
Total Due:	**£84.00**

Payment Terms

BACS Payment to Barclays, Sort Code: 20-50-36, Account No: 00455660, Account Name: Laird Assessors Limited. You can also pay by card by calling 0151 342 0598. For all payments please quote reference number 26-1953697.

This is not a tax invoice - a receipted invoice will follow upon full payment. We will not accept any reduction to our fee through the Detailed Assessment process.

Any requests for addendum reports or letters, including those required for clarification, plus Counsel, Court or other meetings, will be subject to further charges & subject to Civil Procedure Rule 35.6.

Terms: As per our agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. In addition, for unpaid debts up to £999.99. We are allowed to claim compensation of £40.00.