

Our Ref: dfd22085

Your Ref: RJP/ROSS

Date: 23/08/2022

FAO. The Court
C/o Davison Flynn Duke
Chester Street
Birkenhead
CH41 5DL

REPAIRABLE REPORT

Dear Sirs


RE: Road traffic Accident: Tony Ross: 19/08/2022


In accordance with your instructions received on 22/08/2022 requesting us to provide an independent accident damage report, we assessed the damage on 23/08/2022. Vehicle located at Car 2 Go, 220 Price Street, Birkenhead. Our findings are as detailed below:

Make	FORD	Registration	BL19XPO
Model	TRANSIT CUSTOM 280	Status	Repair
Category		Salvage Value	
Repair Cost	£3,625.43	Legal Status	Unroadworthy
Engineer Value	£20,337.00	Impact Magnitude	Moderate



Impact Area





Our Ref: dfd22085

Your Ref: RJP/ROSS

Date: 23/08/2022

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the left hand front.

ENGINEER'S COMMENTS

23/08/2022 - Please note the vehicle is unroadworthy due to the broken/insecure nearside headlamp.

VEHICLE HISTORY CHECK

23/08/2022 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £3,650.00 would be reasonable on this occasion.

Vehicle Data

Retail Value	£20,337.00
Trade Value	£18,337.00
Engineer's Value	£20,337.00
Glass's Code	
VIN	WF0YXXTTGYKK72542
Odometer	17731
Engine	1995
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	

Main new parts required

Front Bumper
L/F Lwr Bumper Cap
L/F Bumper Bracket
Inn Bumper Reinforce
Left Headlamp Assy
L/F Bracket
Sundry Parts

Front Lower Bumper
Frt Bumper Trim Cap
L/F Air Duct
Mounting Clamp
L/F Fog Lamp
Car Care Kit

Repairs required

L/F Wing

L/F W-House Reinf

Additional operations

Check Frt Lock Carrier
Check And Quality Control
Check Technical Info
Paint Front Bumper New Part Paint K1r
Paint L/F Wing Repair Painting <50%
Paint Preparation For Pre-Painting
Estimate Fee
Covid Cleaning
Corrosion Protection Materials External

Check And Clean Car
Check And Road Test
Blend L/F Bracket Surface Paint
Paint Front Lower Bumper New Part Paint K1r
Blend L/F W-House Reinf Surface Paint
Epa Chrg
Bs10125 Compliance Specialist
Ecu Sweep/Resets

Repair Cost Calculations

Hours	15.00
Hourly Rate	£65.00
Total Labour	£975.00
Parts	£1,216.56
Paint/Materials	£594.63
Specialist/Other	£235.00
Sub total	£3,021.19
Vat	£604.24
Total Estimated Cost	£3,625.43





6f9de4aa-aaa8-4c33-8e2f-879444fcdba4(1).jpg



7c2a8137-b232-4ee2-9e87-440a9140bbe2(1).jpg



9d6c1566-6855-4867-901a-0c65c987a6c5.jpg



19a46134-96f3-4af1-a453-05edcccd6960.jpg




890e2207-1129-4de2-8b45-922426b0334f.jpg



2472d425-d4da-4fb9-945d-944bc0689b34.jpg




22485594-21c3-4efc-8f2c-e99d4f5334d8.jpg



66645014-60f8-4b8c-ad96-3703c5ebad32.jpg



b4da53bf-6a37-4869-810f-aa8c2155d578.jpg



c17c6903-253f-4ed0-bb6d-
f0fe910ee64d.jpg



c21aa1e1-0af7-4f60-b3ae-42d167b87556.jpg



d5110390-7d8b-495d-966f-f508adf6ab65.jpg



e1df8bf7-121c-4fd8-a024-
b9ef36137a7b.jpg




705345e7-b000-4c03-8ed4-d8878340ea2f.jpg



951811da-d6f4-4c42-8dc5-5454e30222a9.jpg



fcd91da7-e30d-4f0a-aed9-bea52517907f.jpg




Our Ref: dfd22085

Your Ref: RJP/ROSS

Date: 23/08/2022



f638ef6d-1ac2-4ccb-8de2-48ec6fcd6a85.jpg



Our Ref: dfd22085

Your Ref: RJP/ROSS

Date: 23/08/2022

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: dfd22085

Your Ref: RJP/ROSS

Date: 23/08/2022

FAO. The Court
C/o Davison Flynn Duke
Chester Street
Birkenhead
CH41 5DL

Fee Note

BL19XPO.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £150.00

Sub Total: £150.00

VAT: £30.00

Total Due: £180.00

Payment

Please make cheques payable to Collision Engineers and quote reference dfd22085.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o Davison Flynn Duke confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10