

Our Ref: kbs26081

Your Ref: NAL.506059

Date: 20/05/2026

FAO The Court
C/o Knightsbridge Solicitors
659a Washwood Head Road
Birmingham
B82HJ

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Mr Muhammad Amin: 17/05/2026


In accordance with your instructions received on 20/05/2026 requesting us to provide an independent accident damage report, we assessed the damage on 20/05/2026. Vehicle located at King Street, StokeOnTrent, Staffordshire, ST4 3EF. Our findings are as detailed below:

Make	TOYOTA	Registration	EJ68HMG
Model	AURIS ICON TECH HEV	Status	T/Loss
Category	S	Salvage Value	£1,445.40
Repair Cost	£5,858.21	Legal Status	Unroadworthy
Engineer Value	£7,227.00	Impact Magnitude	Moderate



Impact Area





Our Ref: kbs26081

Your Ref: NAL.506059

Date: 20/05/2026

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand side.

ENGINEER'S COMMENTS

Please note storage charges are currently being incurred.

Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the offside. and the possible wheel, suspension and tyre damage. We do not expect the vehicle to comply with the local licensing authority regulations.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £5,781.60 which represents the pre-accident engineer value of the vehicle of £7,227.00 less the value of the salvage of £1,445.40.

SALVAGE

Under the current salvage categorisation matrix, **within the scope of our inspection**, we consider that this is Category S, (Structural damage) and can be sold as repairable salvage. Further information is available www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £1,445.40. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£7,227.00
Trade Value	£6,432.00
Engineer's Value	£7,227.00
Glass's Code	
VIN	SB1ZS3JE20E452522
Odometer	240741
Engine	1798
Fuel	
Extras	
Condition	Good



Our Ref: kbs26081

Your Ref: NAL.506059

Date: 20/05/2026

Main new parts required

Right Front Wing Emblem (Letters)
Right Front Door Covering Sheet (Skin)
Right Front Door Window Regulator (with Motor)
Right Front Door Outer Handle Seal
Right Front Door Trim Outer Seal
Right Front Door Trim Clip

Right Front Door Shell
Right Front Door Upper Adhesive Foil
Right Front Door Outer Handle
Right Front Door Outer Handle Cover
Right Front Door Trim Support Kit

Repairs required


Right Front Wing
Right B-Post/Sill Panel

Right Rear Door Shell

Additional operations

.Assessment Damage Appraisal Charge
.Pre repair cleaning charge
.Sundries
.System Diagnostic Check (Pre Repair)
.Wash/Clean
Check sill for damage
Corrosion Protection
Corrosion Protection additional panel
Electric / hybrid risk assessment
Hybrid full recharge
Panel repair sundries (including body fi
Second man lift
Paint Right Front Wing, Complete
Paint Right Front Door Outer Handle
Paint Right Rear Door, Complete
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

.Environmental Charge
.QC & Road Test
.System Diagnostic Check (Post Repair)
.Vehicle Care Kit
check alloy wheel for damage
Clamp and Pull
Corrosion Protection additional panel
Door uber decal
Electric / hybrid shutdown and power up
OSF tyre
Polish
Wheel Alignment (check)
Paint Right Front Door, Complete
Paint Right B-Post
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)



Our Ref: kbs26081


Your Ref: NAL.506059

Date: 20/05/2026

Repair Cost Calculations

Hours	31.20
Hourly Rate	£83.28
Total Labour	£2,598.34
Parts	£843.03
Paint/Materials	£857.42
Specialist/Other	£583.05
Sub total	£4,881.84
Vat	£976.37
Total Estimated Cost	£5,858.21






Our Ref: kbs26081

Your Ref: NAL.506059

Date: 20/05/2026






Our Ref: kbs26081

Your Ref: NAL.506059

Date: 20/05/2026






Our Ref: kbs26081

Your Ref: NAL.506059

Date: 20/05/2026






Our Ref: kbs26081

Your Ref: NAL.506059

Date: 20/05/2026








Our Ref: kbs26081

Your Ref: NAL.506059

Date: 20/05/2026






Our Ref: kbs26081

Your Ref: NAL.506059

Date: 20/05/2026






Our Ref: kbs26081

Your Ref: NAL.506059

Date: 20/05/2026






Our Ref: kbs26081

Your Ref: NAL.506059

Date: 20/05/2026








Our Ref: kbs26081

Your Ref: NAL.506059

Date: 20/05/2026





Our Ref: kbs26081

Your Ref: NAL.506059

Date: 20/05/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - M.Inst.IAEA

engineers@collisionengineers.co.uk



Our Ref: kbs26081

Your Ref: NAL.506059

Date: 20/05/2026

FAO The Court
C/o Knightsbridge Solicitors
659a Washwood Head Road
Birmingham
B82HJ

Fee Note

EJ68HMG.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £180.00

Sub Total: £180.00

VAT: £36.00

Total Due: £216.00

Payment

Please make cheques payable to Collision Engineers and quote reference kbs26081.


Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o Knightsbridge Solicitors confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.



Our Ref: kbs26081

Your Ref: NAL.506059

Date: 20/05/2026

Vat number: 262 0937 10