

**Our Ref:** qdos221399

**Your Ref:** CJH/14321/1

**Date:** 23/08/2022

FAO The Court  
C/o QDOS Assistance  
1st Floor, Barfield House  
24-28 Alderly Road  
SK91PL

### **TOTAL LOSS REPORT**

Dear Sirs



**RE: Road traffic Accident: Adama Barry: 13/08/2022**


In accordance with your instructions received on 23/08/2022 requesting us to provide an independent accident damage report, we assessed the damage on 23/08/2022. Vehicle located at Image Based Assessment . Our findings are as detailed below:

|                |                      |                  |                     |
|----------------|----------------------|------------------|---------------------|
| Make           | <b>CITROEN</b>       | Registration     | <b>MK59AXY</b>      |
| Model          | <b>C4 VTR HDI 90</b> | Status           | <b>T/Loss</b>       |
| Category       | <b>N</b>             | Salvage Value    | <b>£100.00</b>      |
| Repair Cost    | <b>£4,755.59</b>     | Legal Status     | <b>Unroadworthy</b> |
| Engineer Value | <b>£1,965.00</b>     | Impact Magnitude | <b>Moderate</b>     |



Impact Area





**Our Ref:** qdos221399

**Your Ref:** CJH/14321/1

**Date:** 23/08/2022

### **DESKTOP ASSESSMENT**

This report has been compiled from a desktop review of the information available relating to this claim.

### **NATURE OF INCIDENT**

The vehicle has suffered moderate collision/impact damage to the right hand front.

### **ENGINEER'S COMMENTS**

Mileage calculated from on line MOT data and converted from KM.

23/08/2022 - Please note the vehicle is unroadworthy due to the damaged offside front wheel.

The vehicle appears to be in good condition with no unrelated damage noted beyond normal wear and tear for the age/mileage.

### **VEHICLE HISTORY CHECK**

23/08/2022 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

### **PRE-INCIDENT CONDITION**

The vehicle is considered to be in good condition for its age and type.

### **SETTLEMENT**


We consider that an equitable settlement would be £1,865.00 which represents the pre-accident engineer value of the vehicle of £1,965.00 less the value of the salvage of £100.00.

### **SALVAGE**

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at [www.abi.org.uk](http://www.abi.org.uk). We suggest that the sale of the salvage will realise in the order of £100.00. **We have not taken any action towards removal of the salvage at this time.**

## **Vehicle Data**

|                  |                          |
|------------------|--------------------------|
| Retail Value     | <b>£1,965.00</b>         |
| Trade Value      | <b>£635.00</b>           |
| Engineer's Value | <b>£1,965.00</b>         |
| Glass's Code     | <b>NHXL</b>              |
| VIN              | <b>VF7LC9HXC9Y552903</b> |
| Odometer         | <b>118000</b>            |
| Engine           | <b>1560</b>              |
| Fuel             | <b>Diesel</b>            |
| Extras           |                          |
| Condition        | <b>Good</b>              |
| Unrelated Damage |                          |



**Our Ref:** qdos221399

**Your Ref:** CJH/14321/1

**Date:** 23/08/2022

#### Main new parts required

Front Bumper Lining  
Right Headlamp, Complete (with Indicator)  
Right One Front Wing and Front Bumper  
Right Front Door Lower Cover  
Right Front Suspension Strut w/Shock Absorber  
Right Front Wheel

Front Bumper Bracket Kit  
Right Front Wing  
Right Front Wing Liner  
Right Front Suspension Arm  
Right Front Steering Knuckle with Hub

#### Repairs required

Right Front Door Shell

#### Additional operations

Repair Method Research Allowance  
System Diagnostic Check (Pre Repair)  
Check and adjust four wheel alignment  
Environmental Charge  
Tyre  
Adjust headlamps  
Paint Right Front Wing, Complete  
Paint Prep. metal (on vehicle without pre-painting)  
Paint Colour mixing (1)


System Diagnostic Check (Post Repair)  
Car Care Kit  
De-Nib/Polish  
Final Inspection & Road Test  
Wash/Clean  
Paint Front Bumper  
Paint Right Front Door, Complete  
Paint Prep. synthetics (combined-operation work)  
Paint Sample colour creation (1)

### Repair Cost Calculations

|                      |                  |
|----------------------|------------------|
| Hours                | <b>16.20</b>     |
| Hourly Rate          | <b>£62.50</b>    |
| Total Labour         | <b>£1,012.50</b> |
| Parts                | <b>£1,974.05</b> |
| Paint/Materials      | <b>£671.44</b>   |
| Specialist/Other     | <b>£305.00</b>   |
| Sub total            | <b>£3,962.99</b> |
| Vat                  | <b>£792.60</b>   |
| Total Estimated Cost | <b>£4,755.59</b> |




Clientsvehicledamage2jpeg-V1(1).jpeg




Clientsvehicledamage4jpeg-V1(1).jpeg






Clientsvehicledamage3jpeg-V1.jpeg



Clientsvehicledamage1jpeg-V1.jpeg



**Our Ref:** qdos221399

**Your Ref:** CJH/14321/1

**Date:** 23/08/2022

### Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA  
engineers@collisionengineers.co.uk



**Our Ref:** qdos221399

**Your Ref:** CJH/14321/1

**Date:** 23/08/2022

FAO The Court  
C/o QDOS Assistance  
1st Floor, Barfield House  
24-28 Alderly Road  
SK91PL

### Fee Note

MK59AXY.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

**Agreed Fee: £100.00**

**Sub Total: £100.00**

**VAT: £20.00**

**Total Due: £120.00**

### Payment

Please make cheques payable to Collision Engineers and quote reference qdos221399.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10