

FAO The Court  
C/o Oakwood Solicitors  
1 West Regent Street  
Glasgow  
Scotland  
G2 1RW

### **TOTAL LOSS REPORT**

Dear Sirs


**RE: Road traffic Accident: Derek Smith: 21/04/2025**


In accordance with your instructions received on 22/04/2025 requesting us to provide an independent accident damage report, we assessed the damage on 01/05/2025. Vehicle located at A76 Recovery, Newton Terrace, Catrine, Mauchline, Ayrshire, KA5 6SA. Our findings are as detailed below:

|                |                            |                  |                     |
|----------------|----------------------------|------------------|---------------------|
| Make           | <b>CITROEN</b>             | Registration     | <b>SL18GNP</b>      |
| Model          | <b>RELAY 35 L3H2 EPRIS</b> | Status           | <b>T/Loss</b>       |
| Category       | <b>N</b>                   | Salvage Value    | <b>£742.60</b>      |
| Repair Cost    | <b>£9,937.72</b>           | Legal Status     | <b>Unroadworthy</b> |
| Engineer Value | <b>£7,426.00</b>           | Impact Magnitude | <b>Moderate</b>     |



Impact Area





**Our Ref:** oak25128

**Your Ref:** S425544.001

**Date:** 01/05/2025

#### **NATURE OF INCIDENT**

The vehicle has suffered moderate collision/impact damage to the right hand rear.

#### **ENGINEER'S COMMENTS**

01/05/2025 - Please note the vehicle is unroadworthy as the rear body has been comprised.

This vehicle has had additional decals fitted, so the PAV has been increased accordingly.

15/5/2025- UPDATED REPORT: - The vehicle owner has disputed our valuation and provided some market research as evidence to dispute the same. On review of this and through conducting our own, we feel the value is £7426.00

#### **VEHICLE HISTORY CHECK**

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

#### **PRE-INCIDENT CONDITION**

The vehicle is considered to be in good condition for its age and type.

#### **SETTLEMENT**


We consider that an equitable settlement would be £6,683.40 which represents the pre-accident engineer value of the vehicle of £7,426.00 less the value of the salvage of £742.60.

#### **SALVAGE**

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at [www.abi.org.uk](http://www.abi.org.uk). We suggest that the sale of the salvage will realise in the order of £742.60 excluding VAT. **We have not taken any action towards removal of the salvage at this time.**

#### **Vehicle Data**

|                  |                          |
|------------------|--------------------------|
| Retail Value     | <b>£6,926.00</b>         |
| Trade Value      | <b>£4,176.00</b>         |
| Engineer's Value | <b>£7,426.00</b>         |
| Glass's Code     |                          |
| VIN              | <b>VF7YC2MFC12G20501</b> |
| Odometer         | <b>120381</b>            |
| Engine           | <b>1997</b>              |
| Fuel             | <b>Diesel</b>            |
| Extras           |                          |
| Condition        | <b>Good</b>              |
| Unrelated Damage |                          |



**Our Ref:** oak25128  
**Your Ref:** S425544.001

**Date:** 01/05/2025

#### Main new parts required

Rear Bumper, Centre  
 Rear Bumper Reinforcement  
 Right Rear Bumper Outer Side Distance-Sensor  
 Rear Panel  
 Right Back Panel Part Corner Panel  
 Right Back Door  
 Right Upper Back Door Hinge  
 Boot Lid/Back Door/Tailgate Badge  
 Right B/Lid/B.Dr/T/gate Protective Moulding  
 Tailgate/Boot Lid Trim Clip

Right Rear Bumper Corner  
 Rear Bumper Repair Kit  
 Right Side Panel Rear Protective Moulding  
 Rear Panel, Upper  
 Right Boot Lid Side Insulation  
 Right B/Lid/T/gate/Back Door Side Weatherstrip  
 Right Lower Back Door Hinge  
 Left Side Type Designation  
 Tailgate/Boot Lid Trim Support Kit

#### Additional operations

Check towbar  
 Corrosion Protection  
 Energy cost supplement  
 Jig, clamp and pull  
 Pre repair cleaning charge (including sa  
 Remove decals for paint  
 Seam Sealant  
 System Diagnostic Check (Post Repair)  
 Vehicle Care Kit  
 Welded / bonded panel (materials )  
 Paint Left Back Door, Complete (Glazed)  
 Paint Rear Panel, Complete  
 Paint Colour mixing (1)

Assessment Damage Appraisal Charge  
 De-nib/ polish  
 Environmental Charge  
 Panel Bonding Kit  
 QC & Road Test  
 Repair method research charge  
 Standard shutdown  
 System Diagnostic Check (Pre Repair)  
 Wash/Clean  
 Paint Right Rear Body Corner Panel, Complete  
 Paint Right Back Door, Complete (Glazed)  
 Paint Prep. metal (on vehicle without pre-painting)  
 Paint Sample colour creation (1)


### Repair Cost Calculations

|                      |                  |
|----------------------|------------------|
| Hours                | <b>29.00</b>     |
| Hourly Rate          | <b>£80.00</b>    |
| Total Labour         | <b>£2,320.00</b> |
| Parts                | <b>£4,138.69</b> |
| Paint/Materials      | <b>£1,306.74</b> |
| Specialist/Other     | <b>£516.00</b>   |
| Sub total            | <b>£8,281.43</b> |
| Vat                  | <b>£1,656.29</b> |
| Total Estimated Cost | <b>£9,937.72</b> |










**Our Ref:** oak25128

**Your Ref:** S425544.001

**Date:** 01/05/2025






**Our Ref:** oak25128  
**Your Ref:** S425544.001

**Date:** 01/05/2025








**Our Ref:** oak25128

**Your Ref:** S425544.001

**Date:** 01/05/2025






**Our Ref:** oak25128

**Your Ref:** S425544.001

**Date:** 01/05/2025







**Our Ref:** oak25128

**Your Ref:** S425544.001

**Date:** 01/05/2025

### Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA  
engineers@collisionengineers.co.uk



**Our Ref:** oak25128

**Your Ref:** S425544.001

**Date:** 01/05/2025

FAO The Court  
C/o Oakwood Solicitors  
1 West Regent Street  
Glasgow  
Scotland  
G2 1RW

### Fee Note

SL18GNP.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

**Agreed Fee: £180.00**

**Sub Total: £180.00**

**VAT: £36.00**

**Total Due: £216.00**

### Payment

Please make cheques payable to Collision Engineers and quote reference oak25128.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o Oakwood Solicitors confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10