

Our Reference

26-1783818/2335766

Your Reference

JMO/43698/1

Date

11th Mar 2026

LAIRD

Total Loss Damage Assessment Report

F.A.O. The Court**C/o Qdos Accident Assistance Ltd**

St Ann's House Parsonage Green

Wilmslow

Cheshire

SK91HG

Dear Sirs


In accordance with your written instructions asking us to provide an accident damage report, we have considered the supplied documentation and our findings are detailed below:

Vehicle Details

Make	Ford
Model	Focus Zetec Tdci
Registration	YJ15POG
Engineer's Value	£3,129.00
Salvage Value	£125.16
Salvage Category	Category S
Status	Total Loss
Legal Status	Unroadworthy
Impact Magnitude	Moderate

Key Details

Claimant	Miss Rene Rogers
Accident Date	03/03/2026
Instruction Date	06/03/2026

Impact Diagram

Our Reference

26-1783818/2335766

Your Reference

JMO/43698/1

Date

11th Mar 2026

LAIRD

Total Loss Damage Assessment Report

Repair Summary

Having examined the damage as presented, we have estimated repair times and methods, which are detailed below. We would recommend the vehicle to be dealt with on a total loss basis. The damage sustained to the vehicle would render the salvage as category 'S' (structural total loss) in accordance with the Salvage Code Of Practice.

We are not aware of any outstanding recovery or storage charges.

We would suggest settlement be sought at a net figure of £3,003.84, being the pre-accident value, less the anticipated salvage value.

The [salvage](#) should be disposed of in accordance with the Code of Practice for the disposal of motor vehicle [salvage](#) produced by the ABI and the vehicle listed on [MIAFTR](#).

Alternatively, the vehicle can be returned to use if repaired to a safe and legal standard, and capable of passing a MOT test thereafter.

As the inspected vehicle is unroadworthy or undriveable and considered beyond economical repair, in order to prevent any issues with safety, legislation, insurance or DVLA, we suggest it should be moved to safe storage.

The salvage has been reviewed by an AQP

Data

We have used [Glass's](#) and [Percayso](#) guides and adverts from sites such as AutoTrader to assist with the valuation of the vehicle and have assumed the mileage reading displayed on the odometer is accurate and the vehicle has its appropriate documentation such as service history & MOT test certificate where applicable.

In order to mitigate losses we have carried out a basic inspection dealing with the vehicle's damaged area; we are happy to accept further instructions to confirm the identity, condition or roadworthiness of the remainder of the vehicle.

We use AI to assist with the compilation of some aspects of this report.

Our Reference

26-1783818/2335766

Your Reference

JMO/43698/1

Date

11th Mar 2026

LAIRD

Total Loss Damage Assessment Report

Statement of Truth

I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

I understand that proceedings for contempt of court may be brought against anyone who makes, or causes to be made, a false statement in a document verified by a statement of truth without an honest belief in its truth.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



Mr Dawson CGL3 VDA CGL2 Salvage Categorisation CAE AMIMI
engineers@laird-assessors.com

Our Reference

26-1783818/2335766

Your Reference

JMO/43698/1

Date

11th Mar 2026

LAIRD

Total Loss Damage Assessment Report

Vehicle Information

Retail Value	£3,129.00	Trade Value	£2,503.00
Engineers Value	£3,129.00	Gearbox	Manual
Valuation Source	Percayso	Body Type	Hatchback
Driven Axle	Front	VIN	WF05XXGCC5FS28133
Colour	Blue	Registration Date	12/08/2015
Vehicle Width	2010	Engine	1.5
Vehicle Length	4358	Fuel	Diesel
Euro NCAP Rating	6	Condition	Fair
Odometer	131201 Miles Viewed		

Unroadworthy Comments

Vehicle will require a geometry check

Door Bar Damage - Door may not act appropriately under a secondary impact

Tyre requires replacement

Our Reference

26-1783818/2335766

Your Reference

JMO/43698/1

Date

11th Mar 2026

LAIRD

Total Loss Damage Assessment Report

Vehicle Comments

Condition Alerts	Not Checked	Finance	No finance agreement recorded
Mileage	No mileage discrepancies	Write Off	No write-off recorded
Stolen	No stolen record	Plate Change	No issues recorded.
Color Changes	No issues recorded.	Origin and Use	No issues recorded.
Keepers	No issues recorded.	MOT History	No issues recorded.
Tax and Sorn	No issues recorded.	At Risk	No risk marker recorded

Our Reference

26-1783818/2335766

Your Reference

JMO/43698/1

Date

11th Mar 2026

LAIRD

Total Loss Damage Assessment Report

New Parts Required

Rear Door Shell (offside)	Sill Panel Cover (plastic) (offside)	Rear Side Panel (offside)
Rear Side Panel Bonding Kit (offside)	Side Glass Repair/bonding Kit (offside)	Rear Tyre Valve (offside)
Sundry Items (2.00%)		

Repairs Required

Rear Wheelarch With Inner Side Panel (offside)

Our Reference

26-1783818/2335766

Your Reference

JMO/43698/1

Date

11th Mar 2026

LAIRD

Total Loss Damage Assessment Report

Additional Operations

4 Wheel Alignment & Adjust	Engineer Fee
Age Allowance	Aries Fee
Car Care Kit	Compilation Fee
Corrosion Protection	Epa Charge
Final Inspection And Road Test	Job Allowance
Mask Front Screen	Miracle Pull
Polish Panels	Pre & Post Diagnostics
Pre Clean Vehicle	Seam Sealant
Std Shutdown	Tyre Rear Offside
Wash / Clean Vehicle	Yard Charge

Our Reference

26-1783818/2335766

Your Reference

JMO/43698/1

Date

11th Mar 2026

LAIRD

Total Loss Damage Assessment Report

Repair Costs Calculations

Hours	50.60
Hourly Rate	£83.28
Total Labour	£4,213.97
Parts	£1,416.17
Paints / Materials	£1,090.92
Specialist / Other Items	£698.81
Sub Total	£7,419.87
VAT	£1,483.97
Total Estimated Cost	£8,903.84

Our Reference

26-1783818/2335766

Your Reference

JMO/43698/1

Date


11th Mar 2026

LAIRD

Total Loss Damage Assessment Report

Repair Costs Analysis

Repair Cost Breakdown



Pre-Accident Value -v- Total Repair Cost

