

Our Ref: htu26019

Your Ref: HS19 MXT

Date: 15/05/2026

FAO The Court
C/O HTU Assessors Ltd
The Old Courthouse
18-22 St Peters Churchyard
Derby
DE1 1NN

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Eco Express: 10/05/2026

In accordance with your instructions received on 12/05/2026 requesting us to provide an independent accident damage report, we assessed the damage on 15/05/2026. Vehicle located at ITV Solutions, Cotton Brook Road, Derby, Derbyshire, DE23 8YJ. Our findings are as detailed below:


Make	HYUNDAI	Registration	HS19MXT
Model	IONIQ PREMIUM HEV	Status	T/Loss
Category	N	Salvage Value	£1,415.50
Repair Cost	£4,215.56	Legal Status	Roadworthy
Engineer Value	£5,662.00	Impact Magnitude	Moderate



Impact Area



Document produced
using the EVA system



Our Ref: htu26019

Your Ref: HS19 MXT

Date: 15/05/2026

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand front.

ENGINEER'S COMMENTS

20% has been deducted from the pre accident valuation due to the vehicle being a previous total loss.

Prior to returning the vehicle to use, we would advise a wheel alignment check is carried out. and the osf tyre is replaced.

VEHICLE HISTORY CHECK

According to the Experian database; Category S total loss claim Structural Damage See the Condition details There are multiple records on the MIAFTR register, the most recent being 20/03/2026, loss dated 28/01/2023

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £4,246.50 which represents the pre-accident engineer value of the vehicle of £5,662.00 less the value of the salvage of £1,415.50.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £1,415.50. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£7,077.00
Trade Value	£6,015.00
Engineer's Value	£5,662.00
Glass's Code	
VIN	KMHC851CVKU143409
Odometer	184153
Engine	1580
Fuel	
Extras	
Condition	Good



Our Ref: htu26019

Your Ref: HS19 MXT

Date: 15/05/2026

Main new parts required

Corrosion Materials - ABP
Right front wing emblem
Front right wing mounting kit
Right front wheel hub cap

Right front wing
Right front wing mount
Right front tyre
Corrosion Materials

Repairs required

Front bumper


Additional operations

Check Post Repair Check
Check QC & Road Test
Paint Front bumper Repaired (K3) Parts removed
Paint Preparation paintwork
Specialist Vehicle Care Kit
Specialist Panel Sundries P/P
Materials

Check Pre Repair Check
Paint Right front wing New Part (I) Parts removed
Paint Right front door Surface (II)
Specialist Assessment Fee
Specialist Hybrid Full Recharge
Specialist Wheel Alignment

Repair Cost Calculations

Hours	21.00
Hourly Rate	£83.28
Total Labour	£1,748.88
Parts	£623.16
Paint/Materials	£794.30
Specialist/Other	£346.63
Sub total	£3,512.97
Vat	£702.59
Total Estimated Cost	£4,215.56




Our Ref: ht26019

Your Ref: HS19 MXT

Date: 15/05/2026






Our Ref: htu26019

Your Ref: HS19 MXT

Date: 15/05/2026






Our Ref: htu26019

Your Ref: HS19 MXT

Date: 15/05/2026






Our Ref: ht26019

Your Ref: HS19 MXT

Date: 15/05/2026






Our Ref: htu26019

Your Ref: HS19 MXT

Date: 15/05/2026






Our Ref: htu26019

Your Ref: HS19 MXT

Date: 15/05/2026






Our Ref: htu26019

Your Ref: HS19 MXT

Date: 15/05/2026






Our Ref: ht26019

Your Ref: HS19 MXT

Date: 15/05/2026





Our Ref: htu26019

Your Ref: HS19 MXT

Date: 15/05/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.

We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - M.Inst.IAEA

engineers@collisionengineers.co.uk