

Our Ref: kbs26011

Your Ref: SA.505793

Date: 21/01/2026

FAO The Court
C/o Knightsbridge Solicitors
659a Washwood Head Road
Birmingham
B82HJ

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Mohammad Irfan: 02/01/2026


In accordance with your instructions received on 20/01/2026 requesting us to provide an independent accident damage report, we assessed the damage on 02/01/2026. Vehicle located at Image based assessment. Our findings are as detailed below:

Make	SKODA	Registration	LN65TNO
Model	OCTAVIA SE BUSINESS	Status	T/Loss
Category	N	Salvage Value	£508.00
Repair Cost	£2,136.68	Legal Status	Roadworthy
Engineer Value	£2,540.00	Impact Magnitude	Light



Impact Area





Our Ref: kbs26011
Your Ref: SA.505793

Date: 21/01/2026

NATURE OF INCIDENT

The vehicle has suffered light collision/impact damage to the rear.

ENGINEER'S COMMENTS

we would advise that the rear bumper is secured before returning to use.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £2,032.00 which represents the pre-accident engineer value of the vehicle of £2,540.00 less the value of the salvage of £508.00.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £508.00. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£2,540.00
Trade Value	£1,473.00
Engineer's Value	£2,540.00
Glass's Code	6V8F
VIN	TMBBJ7NE8G0049752
Odometer	249113
Engine	1968
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	



Our Ref: kbs26011
Your Ref: SA.505793

Date: 21/01/2026

Repairs required

Rear Bumper Lining


Additional operations

.Assessment Damage Appraisal Charge
.Pre repair cleaning charge
.Standard shutdown
.System Diagnostic Check (Post Repair)
.Vehicle Care Kit
check rear bumper reinforcer
Load / Unload vehicle to ramp
Second man lift
Paint Prep. synthetics (on vehicle without pre-painting)
Paint Sample colour creation (1)

.Environmental Charge
.QC & Road Test
.Sundries
.System Diagnostic Check (Pre Repair)
.Wash/Clean
Collection / Delivery
Polish
Paint Rear Bumper k/e
Paint Colour mixing (1)

Repair Cost Calculations


Hours	12.10
Hourly Rate	£83.28
Total Labour	£1,007.69
Parts	£0.00
Paint/Materials	£378.14
Specialist/Other	£394.74
Sub total	£1,780.57
Vat	£356.11
Total Estimated Cost	£2,136.68



Our Ref: kbs26011
Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011

Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011

Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011

Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011

Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011
Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011

Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011

Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011

Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011

Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011
Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011
Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011
Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011

Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011
Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011
Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011

Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011

Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011

Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011

Your Ref: SA.505793

Date: 21/01/2026






Our Ref: kbs26011

Your Ref: SA.505793

Date: 21/01/2026





Our Ref: kbs26011

Your Ref: SA.505793

Date: 21/01/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.

We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk