

Our Ref: htu26005

Your Ref: PX63ZYY

Date: 03/02/2026

FAO The Court
C/O HTU Assessors Ltd
The Old Courthouse
18-22 St Peters Churchyard
Derby
DE1 1NN

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Mr Jamal Hussein Aden: 24/01/2026


In accordance with your instructions received on 02/02/2026 requesting us to provide an independent accident damage report, we assessed the damage on 02/02/2026. Vehicle located at ITV Solutions, Cotton Brook Road, Derby, Derbyshire, DE23 8YJ. Our findings are as detailed below:

Make	NISSAN	Registration	PX63ZYY
Model	MICRA VISIA CVT	Status	T/Loss
Category	N	Salvage Value	£373.20
Repair Cost	£6,060.23	Legal Status	Unroadworthy
Engineer Value	£3,732.00	Impact Magnitude	Moderate



Impact Area





Our Ref: htu26005

Your Ref: PX63ZYY

Date: 03/02/2026

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand side.

ENGINEER'S COMMENTS

20% has been deducted from the pre accident valuation due to the vehicle being a previous total loss.

Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the offside and damaged door handle.

VEHICLE HISTORY CHECK

According to the Experian database; Category S total loss claim Structural Damage See the Condition details Category N total loss claim Non Structural Damage See the Condition details There are multiple records on the MIAFTR register, the most recent being 28/10/2021, loss dated 14/06/2020

PRE-INCIDENT CONDITION


The vehicle is considered to be in average condition for its age and type.

SETTLEMENT

We consider that an equitable settlement would be £3,358.80 which represents the pre-accident engineer value of the vehicle of £3,732.00 less the value of the salvage of £373.20.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £373.20. **We have not taken any action towards removal of the salvage at this time.**



Our Ref: htu26005

Your Ref: PX63ZYY

Date: 03/02/2026

Vehicle Data

Retail Value	£4,665.00
Trade Value	£3,172.00
Engineer's Value	£3,732.00
Glass's Code	4Y4K
VIN	MDHFBUK13U0736788
Odometer	63439
Engine	1198
Fuel	Petrol
Extras	
Condition	Average
Unrelated Damage	


Main new parts required

Right Front Door Shell
Right Rear Door Shell
Rear Bumper Repair Kit
Right Front Door Trim Clip
Right Rear Door Trim Clip

Right Front Door Outer Handle Cover
Rear Bumper Lining
Right Front Door Trim Support Kit
Right Rear Door Trim Support Kit

Repairs required

Right Rear Side Panel



Our Ref: htu26005

Your Ref: PX63ZYY

Date: 03/02/2026


Additional operations

.Assessment Damage Appraisal Charge
.Pre repair cleaning charge
.Standard shutdown
.System Diagnostic Check (Post Repair)
.Vehicle Care Kit
Check sill for damage
Wheel Alignment (check)
Paint Right Rear Door, Complete
Paint Rear Bumper
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)
Sundries

.Environmental Charge
.QC & Road Test
.Sundries
.System Diagnostic Check (Pre Repair)
.Wash/Clean
OSR tyre
Paint Right Front Door, Complete
Paint Right Rear Side Panel, Complete
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)
Set-up time

Repair Cost Calculations

Hours	21.10
Hourly Rate	£83.28
Total Labour	£1,757.21
Parts	£1,568.34
Paint/Materials	£1,253.62
Specialist/Other	£471.02
Sub total	£5,050.19
Vat	£1,010.04
Total Estimated Cost	£6,060.23




Our Ref: htu26005

Your Ref: PX63ZYY

Date: 03/02/2026






Our Ref: htu26005

Your Ref: PX63ZYY

Date: 03/02/2026






Our Ref: htu26005

Your Ref: PX63ZYY

Date: 03/02/2026






Our Ref: ht26005

Your Ref: PX63ZYY

Date: 03/02/2026






Our Ref: ht26005

Your Ref: PX63ZYY

Date: 03/02/2026






Our Ref: htu26005

Your Ref: PX63ZYY

Date: 03/02/2026






Our Ref: htu26005

Your Ref: PX63ZYY

Date: 03/02/2026






Our Ref: htu26005

Your Ref: PX63ZYY

Date: 03/02/2026





Our Ref: htu26005

Your Ref: PX63ZYY

Date: 03/02/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.

We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - M.Inst.IAEA

engineers@collisionengineers.co.uk