

Our Ref: htu26023

Your Ref: SL62VYP

Date: 11/06/2026

FAO The Court
C/O HTU Assessors Ltd
The Old Courthouse
18-22 St Peters Churchyard
Derby
DE1 1NN

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Eddie Ron Clarke: 29/05/2026

In accordance with your instructions received on 10/06/2026 requesting us to provide an independent accident damage report, we assessed the damage on 10/06/2026. Vehicle located at Image-based Assessment. Our findings are as detailed below:


Make	CITROEN	Registration	SL62VYP
Model	C3 WHITE	Status	T/Loss
Category	N	Salvage Value	£160.00
Repair Cost	£2,804.34	Legal Status	Unroadworthy
Engineer Value	£1,600.00	Impact Magnitude	Moderate



Impact Area



Document produced
using the EVA system



Our Ref: htu26023

Your Ref: SL62VYP

Date: 11/06/2026

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the left hand side.

ENGINEER'S COMMENTS

Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the nearside front.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

UNRELATED DAMAGE

We noted the following damage on the vehicle which does not appear to relate to the claim under review and we have therefore classed it as unrelated damage; Rear Bumper.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £1,440.00 which represents the pre-accident engineer value of the vehicle of £1,600.00 less the value of the salvage of £160.00.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £160.00. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£1,704.00
Trade Value	£835.00
Engineer's Value	£1,600.00
Glass's Code	RBL7
VIN	VF7SCKFT0CA588940
Odometer	112451
Engine	1360
Fuel	Petrol
Extras	
Condition	Good



Our Ref: htu26023

Your Ref: SL62VYP

Date: 11/06/2026

Main new parts required

Left Front Wing
Left Front Wing Insulation
Left Front Door Membrane

Left Front Wing Repair Kit
Left Front Wing Panel Screw
Left Front Door Exterior Mirror Cover

Repairs required

Left Front Door Shell


Additional operations

.Assessment Damage Appraisal Charge
.Pre repair cleaning charge
.Standard shutdown
.System Diagnostic Check (Post Repair)
.Vehicle Care Kit
Corrosion Protection
Wheel Alignment (check)
Paint Left Front Wing, Complete
Paint Prep. metal (on vehicle without pre-painting)
Paint Sample colour creation (1)

.Environmental Charge
.QC & Road Test
.Sundries
.System Diagnostic Check (Pre Repair)
.Wash/Clean
De-nib
.Yard Charge
Paint Left Front Door, Complete
Paint Colour mixing (1)

Repair Cost Calculations

Hours	13.80
Hourly Rate	£83.28
Total Labour	£1,149.26
Parts	£383.32
Paint/Materials	£437.74
Specialist/Other	£366.63
Sub total	£2,336.95
Vat	£467.39
Total Estimated Cost	£2,804.34




Our Ref: htu26023

Your Ref: SL62VYP

Date: 11/06/2026







Our Ref: htu26023

Your Ref: SL62VYP

Date: 11/06/2026






Our Ref: htu26023

Your Ref: SL62VYP

Date: 11/06/2026






Our Ref: htu26023

Your Ref: SL62VYP

Date: 11/06/2026






Our Ref: htu26023

Your Ref: SL62VYP

Date: 11/06/2026






Our Ref: htu26023

Your Ref: SL62VYP

Date: 11/06/2026






Our Ref: htu26023

Your Ref: SL62VYP

Date: 11/06/2026





Our Ref: htu26023

Your Ref: SL62VYP

Date: 11/06/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.

We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - M.Inst.IAEA

engineers@collisionengineers.co.uk