

Our Ref: htu26015

Your Ref: YE19UMR

Date: 27/02/2026

FAO The Court
C/O HTU Assessors Ltd
The Old Courthouse
18-22 St Peters Churchyard
Derby
DE1 1NN

TOTAL LOSS REPORT

Dear Sirs



RE: Road traffic Accident: Haawo Nadar Hassan : 17/02/2026

In accordance with your instructions received on 26/02/2026 requesting us to provide an independent accident damage report, we assessed the damage on 26/02/2026. Vehicle located at ITV Solutions, Cotton Brook Road, Derby, Derbyshire, DE23 8YJ. Our findings are as detailed below:


Make	MERCEDES-BENZ	Registration	YE19UMR
Model	A 180 AMG LINE PREM	Status	T/Loss
Category		Salvage Value	£0.00
Repair Cost	£7,555.21	Legal Status	Unroadworthy
Engineer Value	£12,926.00	Impact Magnitude	Moderate to Heavy



Impact Area



Document produced
using the EVA system



Our Ref: htu26015

Your Ref: YE19UMR

Date: 27/02/2026

NATURE OF INCIDENT

The vehicle has suffered moderate to heavy collision/impact damage to the front.

ENGINEER'S COMMENTS

Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the front end.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT

We consider that an equitable settlement would be £12,926.00 which represents the pre-accident engineer value of the vehicle of £12,926.00.


SALVAGE

This vehicle falls outside of the current ABI code of practice for salvage categorisation and therefore no salvage category would apply, however, we consider the salvage could be sold as repairable salvage..

We have not taken any action towards removal of the salvage at this time.

Vehicle Data

Retail Value	£12,926.00
Trade Value	£10,728.00
Engineer's Value	£12,926.00
Glass's Code	
VIN	WDD1770032N067008
Odometer	93727
Engine	1461
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	



Our Ref: htu26015

Your Ref: YE19UMR

Date: 27/02/2026

Main new parts required

Front Bumper Lining
Front Bumper Emblem
Front Bumper Air Guide
Front Bumper Lining Clip
Front Bumper Lining Nut
Front Grille Moulding
Left Bonnet Hinge
Radiator Panel Air Flow Guide
Distance Radar Sensor

Front Bumper Impact Absorber/Filler
Front Bumper Support
Front Bumper Repair kit
Front Bumper Lining Screw
Front Grille
Front Grille Badge
Right Bonnet Hinge
Radar Sensor Bracket
Front Panel Radiator Support Panel

Repairs required

Bonnet


Additional operations

Readjust Bonnet
.Environmental Charge
.QC & Road Test
.System Diagnostic Check (Pre Repair)
.Wash/Clean
Electric / hybrid risk assessment
Load / Unload vehicle to ramp
Paint Front Bumper
Paint Left Front Wing, Complete
Paint Bonnet
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

.Assessment Damage Appraisal Charge
.Pre repair cleaning charge
.System Diagnostic Check (Post Repair)
.Vehicle Care Kit
ADAS Calibration
Electric / hybrid shutdown and power up
Second man lift
Paint Front Grille Moulding
Paint Right Front Wing, Complete
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

Repair Cost Calculations

Hours	27.10
Hourly Rate	£83.28
Total Labour	£2,256.89
Parts	£2,356.30
Paint/Materials	£1,151.92
Specialist/Other	£530.90
Sub total	£6,296.01
Vat	£1,259.20
Total Estimated Cost	£7,555.21




Our Ref: htu26015

Your Ref: YE19UMR

Date: 27/02/2026







Our Ref: htu26015

Your Ref: YE19UMR

Date: 27/02/2026






Our Ref: htu26015

Your Ref: YE19UMR

Date: 27/02/2026







Our Ref: htu26015

Your Ref: YE19UMR

Date: 27/02/2026






Our Ref: htu26015

Your Ref: YE19UMR

Date: 27/02/2026






Our Ref: htu26015

Your Ref: YE19UMR

Date: 27/02/2026





Our Ref: htu26015

Your Ref: YE19UMR

Date: 27/02/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.

We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - M.Inst.IAEA

engineers@collisionengineers.co.uk