

Our Ref: acsp22016

Your Ref: FG15VBA

Date: 24/08/2022

FAO The Court
C/o Accident Specialists
1-3 Brighton Road
Crawley
RH10 6AE

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Faisal Anwar: 18/08/2022


In accordance with your instructions received on 24/08/2022 requesting us to provide an independent accident damage report, we assessed the damage on 23/08/2022. Vehicle located at Priestley Way, Crawley, West Sussex, RH109NT. Our findings are as detailed below:

Make	MERCEDES-BENZ	Registration	FG15VBA
Model	E220 SE BLUETEC AUT	Status	T/Loss
Category	N	Salvage Value	£580.00
Repair Cost	£8,519.21	Legal Status	Unroadworthy
Engineer Value	£5,800.00	Impact Magnitude	Moderate



Impact Area





Our Ref: acsp22016

Your Ref: FG15VBA

Date: 24/08/2022

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the left hand front.

ENGINEER'S COMMENTS

Please note the vehicle is unroadworthy due to the impacted/misaligned nearside front wheel.

VEHICLE HISTORY CHECK

24/08/2022 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £5,220.00 which represents the pre-accident engineer value of the vehicle of £5,800.00 less the value of the salvage of £580.00.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £580.00. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£5,800.00
Trade Value	£2,470.00
Engineer's Value	£5,800.00
Glass's Code	PKF7
VIN	WDD2122012B187666
Odometer	300987
Engine	2143
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	



Our Ref: acsp22016

Your Ref: FG15VBA

Date: 24/08/2022

Main new parts required

Left Front Wing
Left Front Wing Liner, Front
Left Front Wing Panel Clip
Left Front Wing Panel Nut
Left Front Door Lower Seal
Left Front Upper Suspension Arm
Left Front Suspension Strut w/Shock Absorber
Left Front Steering Knuckle
Power Steering Rack Assembly (Rebuilt)

Left Front Wing Repair Kit
Left Front Wing Liner, Rear
Left Front Wing Panel Screw
Bonnet Badge
Left Front Door Window Outer Channel Strip
Left Front Suspension Lower Arm
Left Front Suspension Anti-Roll Bar Linkage
Left Front Wheel Hub with Bearing
Left Front Wheel (Aluminium)


Additional operations

Repair Method Research Allowance
System Diagnostic Check (Pre Repair)
Check and adjust four wheel alignment
Environmental Charge
Tyre
Adjust headlamps
Paint Left Front Wing, Complete
Paint Left Front Door, Complete
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

System Diagnostic Check (Post Repair)
Car Care Kit
De-Nib/Polish
Final Inspection & Road Test
Wash/Clean
Paint Front Bumper
Paint Bonnet
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

Repair Cost Calculations

Hours	19.70
Hourly Rate	£62.50
Total Labour	£1,231.25
Parts	£4,677.15
Paint/Materials	£885.94
Specialist/Other	£305.00
Sub total	£7,099.34
Vat	£1,419.87
Total Estimated Cost	£8,519.21



Our Ref: acsp22016

Your Ref: FG15VBA

Date: 24/08/2022



19852b78-e2f1-4130-ac1c-
fa15c900f1ea.ipa




92252fd7-cf4b-4231-b110-f033d96de401
(1).jpg



caebba81-1e4f-4132-a4ff-
2524866abf55.jpg



d2610b6b-dafb-4e23-bfcb-
c0d698e14847.jpg



Our Ref: acsp22016

Your Ref: FG15VBA


Date: 24/08/2022



200c5c2c-1927-48fc-982e-
cae3ecf90a02.jpg




292f9bab-2b45-47e6-a4fa-
496c9c490f45.jpg



Our Ref: acsp22016

Your Ref: FG15VBA


Date: 24/08/2022



557b8dab-4ae1-40d2-ab35-
cc321fc5873a.jpg



17f8a9cb-794f-49b2-b259-b7c91ed00efa
(1).jpg



Our Ref: acsp22016

Your Ref: FG15VBA

Date: 24/08/2022

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: acsp22016

Your Ref: FG15VBA

Date: 24/08/2022

FAO The Court
C/o Accident Specialists
1-3 Brighton Road
Crawley
RH10 6AE

Fee Note

FG15VBA.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £150.00

Sub Total: £150.00

VAT: £30.00

Total Due: £180.00

Payment

Please make cheques payable to Collision Engineers and quote reference acsp22016.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o Accident Specialists confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10