

Our Ref: ap.qdos25905

Your Ref: AMA/EMS/37635/
1

Date: 25/06/2025

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Mr Joe Ray: 17/06/2025


In accordance with your instructions received on 23/06/2025 requesting us to provide an independent accident damage report, we assessed the damage on 23/06/2025. Vehicle located at Image Based Assessment. Our findings are as detailed below:

Make	VOLKSWAGEN	Registration	MC65MYZ
Model	POLO SE	Status	T/Loss
Category	S	Salvage Value	£600.00
Repair Cost	£12,061.66	Legal Status	Unroadworthy
Engineer Value	£7,490.00	Impact Magnitude	Heavy



Impact Area





Our Ref: ap.qdos25905

Your Ref: AMA/EMS/37635/
1

Date: 25/06/2025

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered heavy collision/impact damage to the left hand rear, and moderate to heavy collision/impact to the right hand side.

ENGINEER'S COMMENTS

The mileage has been calculated from online MOT data.

25/06/2025 - Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the nearside rear.

09/07/2025 UPDATED REPORT: - The vehicle owner has disputed our valuation and provided some market research as evidence to dispute the same. On review of this and through conducting our own, we feel the value is £7,490.00

VEHICLE HISTORY CHECK

According to the Experian database; there is a plate change on record

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £6,890.00 which represents the pre-accident engineer value of the vehicle of £7,490.00 less the value of the salvage of £600.00.

SALVAGE

Under the current salvage categorisation matrix, **within the scope of our inspection**, we consider that this is Category S, (Structural damage) and can be sold as repairable salvage. Further information is available www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £600.00. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£7,099.00
Trade Value	£5,750.00
Engineer's Value	£7,490.00
Glass's Code	83V9
VIN	WVWZZZ6RZGU028800
Odometer	60000
Engine	999
Fuel	Petrol
Extras	
Condition	Good
Unrelated Damage	



Our Ref: ap.qdos25905

Your Ref: AMA/EMS/37635/
1

Date: 25/06/2025

Main new parts required

Right Front Wing
Right Front Wing Insulation
Right Front Door Membrane
Right Front Door Insulation
Left Rear Door Membrane
Right Rear Door Upper Hinge
Right Rear Door Repair Kit
Right Bodyside Front Panel
Left Rear Lamp, Complete
Left Side Glass Repair/Bonding Kit
Left Rear Side Glass Primer
Left Rear Side Glass Applicator
Left Rear Side Glass Activator
Left Side Type Designation
Right Front Door Trim Clip
Right Rear Door Trim Support Kit
Right Rear Door Trim Screw

Right Front Wing Repair Kit
Right Front Door Shell
Right Front Door Repair Kit
Right Rear Door Shell
Right Rear Door Membrane
Right Rear Door Lower Hinge
Right Rear Door Insulation
Right B-Post Cover
Left Rear Side Panel
Right Side Glass Repair/Bonding Kit
Right Rear Side Glass Primer
Right Rear Side Glass Applicator
Right Rear Side Glass Activator
Right Front Door Trim Support Kit
Right Front Door Trim Screw
Right Rear Door Trim Clip

Additional operations


Assessment Damage Appraisal Charge
Corrosion Protection
Energy cost supplement
Identify the presence of ADAS
NSR tyre
QC & Road Test
Seam Sealant
Right Sill dressing (per side)
Sundries
System Diagnostic Check (Pre Repair)
Wash/Clean
Paint Front Bumper
Paint Bonnet
Paint Right B-Post
Paint Right Rear Door, Complete
Paint Left Rear Side Panel, Complete
Paint Tailgate (with Window Frame)
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

Boron Drill
De-nib/ polish
Environmental Charge
Jig, clamp and pull
Panel Bonding Kit
Repair method research charge
Left Sill dressing (per side)
Standard shutdown
System Diagnostic Check (Post Repair)
Vehicle Care Kit
Wheel Alignment (4 wheel)
Paint Right Front Wing, Complete
Paint Right Front Door, Complete
Paint Left Rear Door, Complete
Paint Left Roof Panel, Side
Paint Right Rear Side Panel, Complete
Paint Rear Bumper
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

Repair Cost Calculations

Hours	54.00
Hourly Rate	£80.00
Total Labour	£4,320.00
Parts	£2,626.54
Paint/Materials	£2,226.12
Specialist/Other	£878.72
Sub total	£10,051.38
Vat	£2,010.28
Total Estimated Cost	£12,061.66






Our Ref: ap.qdos25905

Your Ref: AMA/EMS/37635/
1

Date: 25/06/2025






Our Ref: ap.qdos25905

Your Ref: AMA/EMS/37635/
1

Date: 25/06/2025





Volkswagen Polo
1.0 BlueMotion Tech SE Design Euro 6 (s/s) 5dr
2026 MOT

Good price 68,552 miles 2015 (15 reg)

£7,404

📍 Taunton (165 miles)



Volkswagen Polo
1.0 BlueMotion Tech SE Design Euro 6 (s/s) 5dr
Only £20 a Year Road Tax

Good price 67,776 miles 2015 (15 reg)

£7,490

📍 Billericay (192 miles)

4.9 ★

Ad



New All-Electric Ford Puma Gen-E

This cat's gone electric
From £29,995

Book a test drive and unleash your inner big cat with the sleek and powerful New All-Electric Puma Gen-E from £29,995 Recommended OTR price.

New Car Electric

[Learn more](#)

Ford | BRING ON TOMORROW



Volkswagen Polo
1.0 BlueMotion Tech SE Design Euro 6 (s/s) 5dr
F.S.H | NEW MOT | LOW MILES


Good price 60,000 miles 2015 (15 reg)

£7,995

📍 Gloucester (112 miles)

4.9 ★

se X 60,000 - 70,000 miles X 1.0L engine X Petrol X 5 doors X Hatchback X Manual X > Clear all Filter and sort



Our Ref: ap.qdos25905

Your Ref: AMA/EMS/37635/
1

Date: 25/06/2025

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: ap.qdos25905

Your Ref: AMA/EMS/37635/
1

Date: 25/06/2025

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

Fee Note

MC65MYZ.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £100.00

Sub Total: £100.00

VAT: £20.00

Total Due: £120.00

Payment

Please make cheques payable to Collision Engineers and quote reference ap.qdos25905.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10