

Our Ref: qdos221403

Your Ref: CL//13458/1

Date: 23/08/2022

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

REPAIRABLE REPORT

Dear Sirs


RE: Road traffic Accident: John Ferguson: 29/06/2022

In accordance with your instructions received on 23/08/2022 requesting us to provide an independent accident damage report, we assessed the damage on 23/08/2022. Vehicle located at Image Based Assessment . Our findings are as detailed below:


Make	AUDI	Registration	FE62RGE
Model	A4 SLINE BLKED NAV	Status	Repair
Category		Salvage Value	
Repair Cost	£2,965.06	Legal Status	Roadworthy
Engineer Value	£15,160.00	Impact Magnitude	Moderate



Impact Area



Document produced
using the EVA system



Our Ref: qdos221403

Your Ref: CL//13458/1

Date: 23/08/2022

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand side.

VEHICLE HISTORY CHECK

23/08/2022 - According to the Experian database; there is a plate change on record

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £2,975.00 would be reasonable on this occasion.

Vehicle Data

Retail Value	£15,160.00
Trade Value	£12,740.00
Engineer's Value	£15,160.00
Glass's Code	WYYQ
VIN	WAUZZZ8KXFA168963
Odometer	72000
Engine	1968
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	


Main new parts required

Right Front Wing
Right Front Wing Bracket (Front)
Right Front Wing Repair Kit
Right Front Wing Liner
Right Front Wing Foam

Right Front Wing Upper Bracket
Right Front Wing Upper Bracket (Rear)
Right Front Wing Emblem (Letters)
Right Front Wing Closing Panel

Repairs required

Right Front Door Shell



Our Ref: qdos221403

Your Ref: CL//13458/1

Date: 23/08/2022

Additional operations

Repair Method Research Allowance
System Diagnostic Check (Pre Repair)
Car Care Kit
De-Nib/Polish
Final Inspection & Road Test
Paint Front Bumper
Paint Bonnet
Paint Right Front Door Outer Handle
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

System Diagnostic Check (Post Repair)
Alloy Wheel Refurbish
Check and adjust four wheel alignment
Environmental Charge
Wash/Clean
Paint Right Front Wing, Complete
Paint Right Front Door, Complete
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

Repair Cost Calculations

Hours	13.90
Hourly Rate	£62.50
Total Labour	£868.75
Parts	£417.29
Paint/Materials	£909.84
Specialist/Other	£275.00
Sub total	£2,470.88
Vat	£494.18
Total Estimated Cost	£2,965.06

