

Our Ref: qdos221406

Your Ref: CJH/RS/14363/1

Date: 24/08/2022

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

REPAIRABLE REPORT

Dear Sirs



RE: Road traffic Accident: Martin Robertson: 18/08/2022

In accordance with your instructions received on 22/08/2022 requesting us to provide an independent accident damage report, we assessed the damage on 24/08/2022. Vehicle located at Image Based Assessment. Our findings are as detailed below:


Make	FORD	Registration	ST65VNK
Model	FIESTA ST-3 TURBO	Status	Repair
Category		Salvage Value	
Repair Cost	£6,277.46	Legal Status	Unroadworthy
Engineer Value	£10,680.00	Impact Magnitude	Moderate



Impact Area



Document produced
using the EVA system



Our Ref: qdos221406

Your Ref: CJH/RS/14363/1

Date: 24/08/2022

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand side.

ENGINEER'S COMMENTS

24/08/2022 - Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the offside.

VEHICLE HISTORY CHECK

24/08/2022 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £6,300.00 would be reasonable on this occasion.


Vehicle Data

Retail Value	£10,680.00
Trade Value	£9,300.00
Engineer's Value	£10,680.00
Glass's Code	JFNQ
VIN	WF0CXXGAKCFU30545
Odometer	45000
Engine	1596
Fuel	Petrol
Extras	
Condition	Good
Unrelated Damage	

Main new parts required

Right Front Door Window Outer Channel Strip
Right Rear Bumper Side Bracket
Right Rear Side Panel Bonding Kit
Right Side Glass Repair/Bonding Kit
Right Side Panel Liner

Right Sill Panel Cover (Plastic)
Right Rear Side Panel, Complete
Right Rear Side Panel Adhesive Foil
Right Side Panel Foam



Our Ref: qdos221406

Your Ref: CJH/RS/14363/1

Date: 24/08/2022

Repairs required

Right Front Door Shell
Right Rear Wheelarch with Inner Side Panel

Rear Bumper Lining

Additional operations

Jig set up, clamp and pull
Repair Method Research Allowance
System Diagnostic Check (Pre Repair)
Car Care Kit
De-Nib/Polish
Final Inspection & Road Test
Wash/Clean
Paint Right Front Door Outer Handle
Paint Right Rear Side Panel, Complete
Paint Rear Bumper k/e
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

Corrosion Protection Materials
System Diagnostic Check (Post Repair)
Alloy Wheel Refurbish
Check and adjust four wheel alignment
Environmental Charge
Tyre
Paint Right Front Door, Complete
Paint Right Sill Panel Protective Moulding
Paint Tailgate Rear Spoiler
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

Repair Cost Calculations


Hours	38.00
Hourly Rate	£62.50
Total Labour	£2,375.00
Parts	£1,316.28
Paint/Materials	£1,019.94
Specialist/Other	£520.00
Sub total	£5,231.22
Vat	£1,046.24
Total Estimated Cost	£6,277.46



cd91ef79-f29d-4e02-b88f-
d467f13722a7.ipa



000a4143-c902-45b0-91b1-5d078640b958
(1).jpg




Our Ref: qdos221406

Your Ref: CJH/RS/14363/1


Date: 24/08/2022



8c45e2c4-5b25-4bb5-bcf3-
15dd5749ba5d.jpg




33acd914-2a51-4081-87fa-201e8406cd8c
(1).jpg



Our Ref: qdos221406

Your Ref: CJH/RS/14363/1


Date: 24/08/2022



390f0b8c-863f-4089-955e-
a1002deb7fde.ipa



2164b096-7614-47f2-b7a7-
1caee7c5318d.jpg



Our Ref: qdos221406
Your Ref: CJH/RS/14363/1


Date: 24/08/2022



482645b0-67bc-4113-9e5a-
3e79a91b027c.ipa



973089db-ab9a-4474-8360-5ab2a9b7ebc4.jpg



Our Ref: qdos221406

Your Ref: CJH/RS/14363/1

Date: 24/08/2022

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: qdos221406

Your Ref: CJH/RS/14363/1

Date: 24/08/2022

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

Fee Note

ST65VNK.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £100.00

Sub Total: £100.00

VAT: £20.00

Total Due: £120.00

Payment

Please make cheques payable to Collision Engineers and quote reference qdos221406.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10