

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Mr Imran Abid: 18/11/2024


In accordance with your instructions received on 19/11/2024 requesting us to provide an independent accident damage report, we assessed the damage on 20/11/2024. Vehicle located at Image Based Assessment. Our findings are as detailed below:

Make	MERCEDES-BENZ	Registration	OV17NXA
Model	E 220 D AMG LINE AUT	Status	T/Loss
Category	S	Salvage Value	£3,355.00
Repair Cost	£11,886.78	Legal Status	Unroadworthy
Engineer Value	£15,250.00	Impact Magnitude	Moderate to Heavy



Impact Area





Our Ref: qdos241668

Your Ref: KC/33016/1

Date: 20/11/2024

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate to heavy collision/impact damage to the right hand side.

ENGINEER'S COMMENTS

20/11/2024 - Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the offside.

27/11/2024 - UPDATED REPORT: - The vehicle owner has disputed our valuation and provided some market research as evidence to dispute the same. On review of this and through conducting our own, we feel the value is £15250.00

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £11,895.00 which represents the pre-accident engineer value of the vehicle of £15,250.00 less the value of the salvage of £3,355.00.

SALVAGE

Under the current salvage categorisation matrix, **within the scope of our inspection**, we consider that this is Category S, (Structural damage) and can be sold as repairable salvage. Further information is available www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £3,355.00. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	
Trade Value	
Engineer's Value	£15,250.00
Glass's Code	WM83
VIN	WDD2130042A206296
Odometer	88551
Engine	1950
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	



Our Ref: qdos241668

Your Ref: KC/33016/1

Date: 20/11/2024

Main new parts required

Right Rear Door Shell
Right Rear Door Insulation
Right Side Panel Reinforcement
Right Rear Wheelarch, Outer
Rear Window Repair/Bonding Kit
Right Rear Suspension Upper Front Arm
Right Rear Suspension Lower Front Arm
Right Rear Door Trim Support Kit

Right Rear Door Outer Handle
Right Rear Side Panel
Right Side Panel Insulation
Right Side Panel Liner
Rear Window Primer
Right Rear Suspension Upper Rear Arm
Right Rear Shock Absorber
Right Rear Door Trim Screw

Repairs required


Right Sill Panel Cover (Plastic)

Rear Bumper Lining

Additional operations

Body Filler
Sill dressing (per side)
De-nib/ polish
Energy cost supplement
Estimate/Assessment Charge
OSR tyre
PPE equipment
Research Methods
Seam Sealant
Sundries
System Diagnostic Check (Post Repair)
Trial panel fit (second time)
Wash/Clean
Water test
Second man lift
Paint Right Front Door, Complete
Paint Right Rear Door, Complete
Paint Right Rear Side Panel, Complete
Paint Rear Bumper k/e
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

Boron Drill
Corrosion Protection
Touch up bolts
Environmental Charge
Jig, clamp and pull
Panel Bonding Kit
QC & Road Test
Sanitising of damaged vehicle
Standard shutdown
Swap wheel with spare wheel
System Diagnostic Check (Pre Repair)
Vehicle Care Kit
Wash/Clean
Wheel Alignment (4 wheel)
Paint Right A-Post, Upper
Paint Right Front Door Outer Handle
Paint Right Rear Door Outer Handle
Paint Right Fuel Filler Lid
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)



Our Ref: qdos241668


Your Ref: KC/33016/1

Date: 20/11/2024

Repair Cost Calculations

Hours	62.70
Hourly Rate	£80.00
Total Labour	£5,016.00
Parts	£2,737.35
Paint/Materials	£1,166.10
Specialist/Other	£986.20
Sub total	£9,905.65
Vat	£1,981.13
Total Estimated Cost	£11,886.78






Our Ref: qdos241668

Your Ref: KC/33016/1

Date: 20/11/2024





Our Ref: qdos241668

Your Ref: KC/33016/1

Date: 20/11/2024

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: qdos241668

Your Ref: KC/33016/1

Date: 20/11/2024

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

Fee Note

OV17NXA.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £100.00

Sub Total: £100.00

VAT: £20.00

Total Due: £120.00

Payment

Please make cheques payable to Collision Engineers and quote reference qdos241668.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10