

Assessment Number: TO124580
Version: vbra40bb/1

Full Report
Printed: 23/06/2022

Summary Information

Claim

Authorisation Status:	Interim	Date of Incident:	01/06/2022
Work Provider:	Bodyshop/Repairer	Able to Authorise Repairs:	TBA
Claim Reference:	13222/1	Repairs Authorised?	TBA
Policy Number:		VAT Portion Payable:	NonTaxable
Other Reference:		Repairer:	
		Estimated Repair Time (Working Days):	0.0

Vehicle Details

Vehicle

Manufacturer:	KIA
Model:	SPORTAGE KX-3
Model Sheet Number:	2860
Engine:	2.0 LTR 130/136KW
Registration Number:	YX67NYB
VIN Number:	U5YPH813SHL366184
Registration Month:	September
Registration Year:	2017
Odometer:	27325 miles
Colour:	SILVER
Paint Code:	E5B
Build Date:	FROM 08/2017
Selection Type:	AudaVIN+

Model Specs

FROM 08/2017
AUTO AIR CON
AUXILIARY HEATER PTC
TINT GLASS (PRIVACY)
LANE CHANGING ASSIST
ANTI MISTING SYSTEM
FRT SCREEN/DEFROSTER
REMOTE CENTRAL LOCK
PULSE GENERATOR
ELECT FOLDING MIRROR
MIRROR W/NDICATOR
RADIO WITH DISPL 8.0
VOICE RECOGNIT SYS
NAVIGATION SYSTEM
SYSTEM BLUETOOTH
SUBWOOFER
FOG LAMPS
INTERIOR EQUIP LEATH
LEATHER SEATS
FRT/RR HEATED SEATS
RAIN SENSOR
LIGHT SENSOR
GRILLE BLACK SHINE
ANTI-THEFT ALARM
EQUIPMENT SATIN
CHROME DOOR HANDLES
REAR PARKING SYSTEM
REARVIEW CAMERA
EQUIP BLACK SHINE
2.0 LTR 130/136KW
EMISSION STD EURO 6
AUTO GEARBOX 6 SPEED
HD SHOCK ABSORBER
ELECT POWER STEERING
TYRES 245/45 HR 19
WHEELS 7.5J X 19 ALU

Assessment Number: TO124580
Version: vbra40bb/1

Full Report
Printed: 23/06/2022

TYRE PRESSURE SENSOR
ESP
FOUR WHEEL DRIVE
HEAD AIRBAG
SIDE AIRBAGS
ELECTRIC SUNROOF
ROOF RAILS
COMBI INSTRUMENT LCD
PRODUCTION SLOVAKIA
LED DRL HEADLAMPS
TWO COAT METALLIC
PREPARE OFF VEHICLE
SUN PROTECTION
CLEAR COAT HARD

Vehicle Condition

Vehicle Status


Pre-Accident Condition: Good
Steering Rim Ply: Not testable
Brakes Pedal Travel: Satisfactory
Place of Inspection:
Pre-Accident Damage:

Severity of Impact:
Vehicle Status on Inspection:
Date of Inspection: 17/06/2022


Tyres Condition: Poor
Tyres - Tread Depth (MM):

		Left Tyre		Right Tyre	
	Axes	Depth	Depth		
LHF	0	2.0	2.0	RHF	
LHR	1	3.0	3.0	RHR	

Damage Areas:



Direction of Impact:



Assessment Number: TO124580
Version: vbra40bb/1

Full Report
Printed: 23/06/2022

Addresses

Assessor

Terry Orr ATA VDA
Lincoln Way
Salthill Ind Est
Clitheroe
Lancs
BB7 1QD
Business Tel : 01200 444455
Fax Tel : 01200 443555
Email Address : terry@jamesalpe.co.uk

Insured

Mr Joshua Redfern
28 Kirkdale
Burnley
BB112HS
Home Tel : 07927166276
Mobile Tel : 07928364281

Repairer

James Alpe LTD
Lincoln Way
Salthill ind est
Clitheroe
Lancs
BB7 1QD
Business Tel : 01200 444455
Fax Tel : 01200 443555
Email Address : info@jamesalpe.co.uk

User Driver

Cost Summary

Total Labour	£205.00
Total Parts	£96.11
Additional Costs	£710.00
Grand Total Exc VAT:	£1,011.11
20 % VAT:	£202.22
Grand Total Inc VAT:	£1,213.33
Excess:	£0.00

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price = £50.00/HR

Repair / Guide

Number	Description	Work Units
NO NUMBER	WASH VEHICLE	3.0
NO NUMBER	CHECK FUNCTION OF ABS SYSTEM	3.0
52951R00)	R + R LEFT FRONT WHEEL	1.0
52951R00)	R + R RIGHT FRONT WHEEL	1.0
52910R00)	R + R L/F TYRE	1.0
	(WHEEL REMOVED)	
	INCLUDES: BALANCE WHEEL	
52910R00)	R + R R/F TYRE	1.0
	(WHEEL REMOVED)	
	INCLUDES: BALANCE WHEEL	
52951R0R)	R + R LEFT REAR WHEEL	1.0
52951R00)	R + R RIGHT REAR WHEEL	1.0
52910R00)	R + R L/R TYRE	1.0
	(WHEEL REMOVED)	
	INCLUDES: BALANCE WHEEL	
52910R00)	R + R R/R TYRE	1.0

**TEL: JAMES ALPE LIMITED FAX:
01200 444455 LINCOLN WAY 01200 443555
SALTHILL INDUSTRIAL ESTATE
CLITHEROE, LANCASHIRE, BB7 1QD**

Assessment Number: TO124580
Version: vbra40bb/1

Full Report
Printed: 23/06/2022

	(WHEEL REMOVED)	
	INCLUDES: BALANCE WHEEL	
52910R0B)	R + R TYRE/WHEEL (ADD/WORK)	2.0
	BSI COMPLIANCE Renew	
1000	FINAL CHECKS ROAD TEST	10.0*
1000	CHECK JOB ALLOWANCE	5.0*
1000	CHECK CLEAN VEHICLE	5.0*
1000	CHECK NSF SUSPENSION	5.0*
Total Work Units		41.0
Total Panel / Mechanical Labour		4.10 HRS
		£205.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = £50.00/HR

Repair /Guide	Description	
Number		Work Units

MATERIAL COST - PAINT

COST

Total Paint Cost	£0.00
Sundry Paint Material	£0.00
Pre-Painting Sundry Materials	£0.00
Total Excluding Pearlescent Uplift	£0.00
Pearlescent Uplift @ 0.0%	£0.00
Discounted by 100%	£0.00
Total Paint And Material Cost	£0.00

PARTS

Price Valid: 14/02/2022

Guide No.	Description	Part Number	Bet.	Held Date	Price
7229	L/F INF PRESS SENSOR	52933D9100	0%		£57.86
1000	BSI COMPLIANCE	Renew	0%		£35.00 *
Sub Total					£92.86
Deduction from RRP					£0.00
Sundry Parts					£3.25
Total Parts					£96.11

**TEL: JAMES ALPE LIMITED FAX:
01200 444455 LINCOLN WAY 01200 443555
SALTHILL INDUSTRIAL ESTATE
CLITHEROE, LANCASHIRE, BB7 1QD**

Assessment Number: TO124580
Version: vbra40bb/1

Full Report
Printed: 23/06/2022

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras			
	Description	Betterment	Price
	DELIVERY/COLLECTION Specialist	0%	£150.00
	E.P.A. CHARGE Specialist	0%	£22.00
	METHODS RESEARCH Specialist	0%	£32.00
	4 WHEEL ALIGNMENT Specialist	0%	£95.00
	CAR CARE KIT Specialist	0%	£8.00
	TYRE DISPOSAL Specialist	0%	£5.00
	PRE & POST SWEEP Specialist	0%	£90.00
	COVID CLEAN ARRIVAL	0%	£20.00
	COVID CLEAN DEPART	0%	£20.00
	COVID PPE Specialist	0%	£8.00
	ASSESSMENT FEE Specialist	0%	£60.00
	OPERATIONAL ENERGY	0%	£25.00
	OVERHEAD		
	TYRES X1 Specialist	0%	£175.00
	Total Extras		£710.00

Calculation

23/06/2022

Labour			
	Total Panel/Mechanical	£205.00	
	Total Paintwork	£0.00	
Total Labour			£205.00
Total Paint/Material Costs			£0.00
Total Parts			£96.11
Additional Costs			
	Cost of Specialist	£710.00	
Total Additional Costs			£710.00
Grand Total Excl VAT			£1,011.11
	VAT @ 20 %		£202.22
Grand Total Incl VAT			£1,213.33
	Excess		£0.00

Assessment Notes

No assessment notes entered.

**TEL: JAMES ALPE LIMITED FAX:
01200 444455 LINCOLN WAY 01200 443555
SALTHILL INDUSTRIAL ESTATE
CLITHEROE, LANCASHIRE, BB7 1QD**

Assessment Number: TO124580

Full Report

Version: vbra40bb/1

Printed: 23/06/2022
