SCOPE
Petroleum Services

EXCAVATOR EQUIPMENT INSPECTION CHECK LIST

Annex to certificate N°: ST-4536-25

Date of inspection: 05/march/2023

	DESCRIPTION	CONDITION OR REMARKS
0	**GENERAL DESCRIPTION OF THE EQUIPMENT**	
0.0	Description: Excavator Equipment	**EXCAVATOR EQUIPMENT** **Manufacturer: HITACHI** **MODEL: ZX200** **REG NO: A 26286-Basra** **CHASSIS NO: HCM1G600P00117888**
1	**SECTION**	
1.1	Manufacturers operation manual	N/A
1.2	Operator competency certificate	OK
1.3	Hand Brake Interlock	OK
1.4	Hydraulic oil level	OK
1.5	Condition of oil	OK
1.6	System and hoses	OK
1.7	Lubrication	OK
1.8	Engine Indication	OK
1.9	Boom structure	OK
1.10	Control levers	OK
1.11	Track Roller frame	OK
1.12	Wear , damage , cracks , leaks	OK
1.13	Bucket	OK
1.14	Pins , Grease lines	OK
1.15	Tracks/ Tyres / Crawler	OK
1.16	Windows / Mirrors / Lights	OK
1.17	Undercarriage (including leaks)	OK
1.18	Belts / Hoses / Bolts	OK
1.19	Electrical System	OK
1.20	Power Train	OK
1.21	Power Unit	OK
1.22	Power Link	OK
1.23	Motion Alarm	OK
1.24	Counter Weight	OK
1.25	Main Frame	OK
1.26	Fire Extinguisher	OK
1.27	First Aid	OK

Scope petroleum services
SCOPE Petroleum Services
Lifting Department

Scope Petroleum Services
SCOPE Petroleum Services
Quality Control


Address: Burjesia-Tuba Area -After the Bridge Hamoud El-Wabdan
Contacts:operation@scopeps.com/sales@scopeps.com
Phone: +964 7803222202 / +964 7803773775

EXCAVATOR EQUIPMENT INSPECTION CHECK LIST

Annex to certificate N°: ST-4536-25

Date of inspection: 05/march/2023

Comment:

















Surveyor's Name: Mohamed Abdel Halim

Signature:

Scope Petroleum Services Quality Control

Scope petroleum services Lifting Department

Address: Burjesia-Tuba Area -After the Bridge Hamoud El-Wabdan
Contacts:operation@scopeps.com/sales@scopeps.com
Phone: +964 7803222202 / +964 7803773775

SCOPE
Petroleum Services

Certificate of Thorough Examination & NDE for Hydraulic Excavator

Date of Through Examination: 05/march/2023			Certificate number: ST-4536-25
Name and Address of employer for whom the thorough examination was made: MSK Co., BASRA , IRAQ			Address of premises at which the examination was made: MSK YARD
Identification NO	**QTY**	**Description**	**Date of next examination**
HCM1G600P00117888	1	**EXCAVATOR EQUIPMENT** MANUFACTURER: HITACHI MODEL: ZX200 REG NO: A 26286-Basra CHASSIS NO: HCM1G600P00117888 BUCKET S/N: 02 EXAMINED IN ACCORDING TO BS EN 474-5:2006+A3:2013	04/March/2024

Tools Details

Tools Details	Measuring Tape S/N: SCP-L-001	Vernier Calliper S/N: SCP-L-002

NDT Details

Standard: BS EN ISO 9934-1	Equipment type: YOKE S\N: 3291K	Contrast Media: WHITE
Procedure: SPS-IMS-P027	Method: WET	Indicator: MAG INK

Result	MPI was carried out on the critical stress areas of bucket were found free from any surface defects

					Was the examination carried out:				
Is this the first examination after installa	YES		NO	√	Within an interval of 6 months?	YES		NO	√
					Within an interval of 12 months?	YES	√	NO	
If the answer to the above question is YE	YES		NO		In accordance with an examinatio scheme?	YES	√	NO	
has the equipment been installed correct					After the occurrence of exceptiona circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the def

Particulars of any repair, renewal or alteration required to remedy the defect identified above: (NONE)

Particulars of any tests carried out as part of the examination: (Visual , Function , Performance , MPI Tests)

Is This Equipment Safe To Operate?	YES	√	NO	

Name of person making this report: Mohamed Abdel Halim	Name of person authenticating this report: Mostafa Shama
Signature:	

Name of employer of persons making and authenticating this report:
Scope petroleum services: lifting@scopeps.com

Scope petroleum services Lifting Department

Scope Petroleum Services Quality Control