




Exp. initial texture of DC06



Exp. Texture after simple shear strain of $\gamma_{12}=1.0$ for DC06




Simple shear after deformation of $\gamma_{12}=1.0$ for DC06 by code 3 with Taylor model.




Difference from measured texture after simple shear strain of $\gamma_{12}=1.0$ calculated by versch program: 7.62406400

Pure shear after deformation of $\gamma_{12}=\gamma_{21}=0.5$ for DC06 by code 3 with Taylor model.




Difference from measured texture after simple shear strain of $\gamma_{12}=1.0$ calculated by versch program: 6.86556400

Simple shear after deformation of $\gamma_{12}=1.0$ for DC06 by code 6 with Taylor model




Difference from **measured texture after simple shear strain of $\gamma_{12}=1.0$** calculated by versch program: 3. 23580100

Pure shear after deformation of $\gamma_{12}=\gamma_{21}=0.5$ for DC06 by **code 6 with Taylor model**.




Difference from **measured texture after simple shear strain of $\gamma_{12}=1.0$** calculated by versch program: 6. 86285700

Simple shear after deformation of $\gamma_{12}=1.0$ for DC06 by **code 5 with Taylor model**



Difference from **measured texture after simple shear strain of $\gamma_{12}=1.0$** calculated by versch program: 3. 23807500

Pure shear after deformation of $\gamma_{12}=\gamma_{21}=0.5$ for DC06 by **code 5 with Taylor model**.



Difference from **measured texture after simple shear strain of $\gamma_{12}=1.0$** calculated by versch program: 6. 86556400

According to the correct code (**code 5** and **code 6**), the difference of the texture after simple shear and pure shear on the ODFs is a rotation about ND (reflected in angle φ_1), which is consistent to the real deformation.