



D38 human-in-the-loop correction: markup becomes traceable 3D evidence


Human review markup (B35 top view)



D38.2 corrected station view



GIS-row correction review



1 · Register markup NCC 0.94 / 0.92 scale 0.94	2 · Invert camera mapping 7 marked regions → model-world coordinates	3 · Diagnose 3 false cabinet groups 3 GIS gaps + fire room	4 · Preserve provenance 9 cabinet objects moved to quarantine, not deleted	5 · Rebuild + review GIS gaps + fire facilities; D38.1 yaw error → D38.2
---	---	---	---	---

Figure 6 · Sparse human feedback supplies an error signal; the agent performs evidence registration, diagnosis, geometric correction, and provenance-preserving quarantine.