


Comments:

## **Quality Assurance Management, Inc.**

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

## **Oxygen Test Report**




Client:	TEST CLIENT		Analyzer:	Delta F	
Facility:	QAM HQ		Serial Number:	PT-23473	-V6
Tool / Equipment ID:			Calibration Due:	Not calibra	ated
System:			Instrument Flow:	2.0	SCFH
Source ID:			Start Time/Date:	10:15 06/19/21	
Test Point ID:			Stop Time/Date:	15:24 06/21/21	
Test Gas:			Test Duration:	5 hours 9 minutes 6 seconds	
Test Flow:	4.3	SCFH	Average:	-0.5	PPB
Technician:			Final:	0.4	PPB
			Specification:	20	PPB



## **Quality Assurance Management, Inc.**

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

## **Moisture Test Report**



Client:	TEST CLIENT		Analyzer:	Tracer 2	
Facility:	QAM HQ		Serial Number:	17481-44-	1
Tool / Equipment ID:			Calibration Due:	02/23/202	3
System:			Instrument Flow:	2.3	SCFH
Source ID:			Start Time/Date:	10:15 06/1	9/21
Test Point ID:			Stop Time/Date:	15:24 06/2	21/21
Test Gas:			Test Duration:	5 hours 9	minutes 6 seconds
Test Flow:	4.3	SCFH	Average:	4.9	PPB
Technician:			Final:	1.1	PPB
			Specification:	20	PPB

Comments:	
-----------	--