


Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Oxygen Test Report



Client:	TEST CLIENT		Analyzer:	Delta F	
Facility:	QAM HQ		Serial Number:	PT-18690	-V6
Tool / Equipment ID:	TEST123		Calibration Due:	7/2021	
System:	PN2		Instrument Flow:	2.0	SCFH
Source ID:	TST-SRC-ID		Start Time/Date:	10:39 03/0)1/21
Test Point ID:	PN2 POC		Stop Time/Date:	11:40 03/0)1/21
Test Gas:	Nitrogen		Test Duration:	1 hours 0	minutes 50 seconds
Test Flow:	4.3	SCFH	Average:	0.0	PPB
Technician:	JCH		Final:	0.0	PPB
			Specification:	20	PPB


Comments:	Save graph test
-----------	-----------------



Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Moisture Test Report



Client:	TEST CLIENT	Analyzer:	Tracer 2	
Facility:	QAM HQ	Serial Number:	17367-44-	1
Tool / Equipment ID:	TEST123	Calibration Due:	8/2021	
System:	PN2	Instrument Flow:	2.3	SCFH
Source ID:	TST-SRC-ID	Start Time/Date:	10:39 03/0	01/21
Test Point ID:	PN2 POC	Stop Time/Date:	11:40 03/0	01/21
Test Gas:	Nitrogen	Test Duration:	1 hours 0	minutes 50 seconds
Test Flow:	4.3 SCFH	Average:	24.8	PPB
Technician:	JCH	Final:	24.3	PPB
		Specification:	20	PPB

Comments:	Save graph test
-----------	-----------------