


## **Quality Assurance Management, Inc.**

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

## **Oxygen Test Report**



Client: TEST CLIENT Analyzer: Delta F Facility: QAM HQ Serial Number: PT-18690-V6 Tool / Equipment ID: TEST123 Calibration Due: 7/2021 System: PN2 Instrument Flow: 2.0 **SCFH** Source ID: TST-SRC-ID Start Time/Date: 10:37 02/25/21 Stop Time/Date: 11:48 02/25/21 Test Point ID: PN2 TP Test Gas: Nitrogen Test Duration: 1 hours 11 minutes Test Flow: 4.3 **SCFH PPB** Average: 0.0 Final: 0.0 Technician: JCH **PPB** Specification: 20 **PPB** 


Comments: First test using only the touchscreen and on-screen keyboard



**Quality Assurance Management, Inc.** 

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

## **Moisture Test Report**



Client: TEST CLIENT Analyzer: Tracer 2 Facility: QAM HQ Serial Number: 17367-44-1 Tool / Equipment ID: TEST123 Calibration Due: 8/2021 Instrument Flow: 2.3 System: PN2 **SCFH** Source ID: TST-SRC-ID Start Time/Date: 10:37 02/25/21 Test Point ID: PN2 TP Stop Time/Date: 11:48 02/25/21 Test Gas: Nitrogen Test Duration: 1 hours 11 minutes Test Flow: 4.3 **SCFH PPB** Average: 0.5 Final: 0.0 Technician: JCH **PPB** Specification: 20 **PPB** 

Comments: First test using only the touchscreen and on-screen keyboard