


Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Oxygen Test Report



Client:	TEST CLIENT	Analyzer:	Delta F	
Facility:	QAM HQ	Serial Number:	PT-18690-V6	
Tool / Equipment ID:	test tool	Calibration Due:	7/2021	
System:	PN2	Instrument Flow:	2.0	SCFH
Source ID:	test source	Start Time/Date:	16:02 03/01/21	
Test Point ID:	PN2 test point	Stop Time/Date:	07:05 03/02/21	
Test Gas:	Nitrogen	Test Duration:	15 hours 2 minutes	
Test Flow:	4.3 SCFH	Average:	0.0	PPB
Technician:	JCH	Final:	0.0	PPB
		Specification:	20	PPB

Comments:	
-----------	--




Comments:

Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Moisture Test Report



Client:	TEST CLIENT	Analyzer:	Tracer 2	
Facility:	QAM HQ	Serial Number:	17367-44-1	
Tool / Equipment ID:	test tool	Calibration Due:	8/2021	
System:	PN2	Instrument Flow:	2.3 SCFH	
Source ID:	test source	Start Time/Date:	16:02 03/01/21	
Test Point ID:	PN2 test point	Stop Time/Date:	07:05 03/02/21	
Test Gas:	Nitrogen	Test Duration:	15 hours 2 minutes	
Test Flow:	4.3 SCFH	Average:	2.3 PPB	
Technician:	JCH	Final:	3.1 PPB	
		Specification:	20 PPB	