


Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Oxygen Test Report



Client:	TEXAS INSTRUMENTS		Analyzer:	Delta F	
Facility:	RFAB		Serial Number:	PT-18690-V6	
Tool / Equipment ID:	TESTING123		Calibration Due:	7/2021	
System:	PN2		Instrument Flow:	2.0	SCFH
Source ID:	TEST SOURCE		Start Time/Date:	08:37 02/24/21	
Test Point ID:	PN2 POC		Stop Time/Date:	08:42 02/24/21	
Test Gas:	Nitrogen		Test Duration:	5 minutes	
Test Flow:	4.3	SCFH	Average:	0.0	PPB
Technician:	JCH		Final:	0.0	PPB
			Specification:	20	PPB


Comments: This is a test of the touchscreen



Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Moisture Test Report



Client: TEXAS INSTRUMENTS Analyzer: Tracer 2 Facility: RFAB Serial Number: 17367-44-1 Tool / Equipment ID: TESTING123 Calibration Due: 8/2021 System: PN2 Instrument Flow: 2.3 **SCFH** Source ID: TEST SOURCE Start Time/Date: 08:37 02/24/21 Test Point ID: PN2 POC Stop Time/Date: 08:42 02/24/21 Test Gas: Nitrogen Test Duration: 5 minutes Test Flow: 4.3 **SCFH** Average: 5.2 **PPB** Technician: JCH Final: 5.2 **PPB** Specification: 20 **PPB**

Comments: This is a test of the touchscreen