


**Quality Assurance Management, Inc.** 

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

## **Oxygen Test Report**



Client:	TEST CLIENT	Analyzer:	Delta F	
Facility:	HQ	Serial Number:	PT-18690-V6	
Tool / Equipment ID:	TEST123	Calibration Due:	7/2021	
System:	PN2	Instrument Flow:	2.0	SCFH
Source ID:	TEST-SOURCE	Start Time/Date:	12:08 02/24/21	
Test Point ID:	PN2 LINE	Stop Time/Date:	13:02 02/24/21	
Test Gas:	Nitrogen	Test Duration:	53 minutes	
Test Flow:	4.3 SCFH	Average:	0.0	PPB
Technician:	JCH	Final:	0.0	PPB
		Specification:	20	PPB


Comments:	



**Quality Assurance Management, Inc.** 

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

## **Moisture Test Report**



Client:	TEST CLIENT	Analyzer:	Tracer 2	
Facility:	HQ	Serial Number:	17367-44-1	
Tool / Equipment ID:	TEST123	Calibration Due:	8/2021	
System:	PN2	Instrument Flow:	2.3	SCFH
Source ID:	TEST-SOURCE	Start Time/Date:	12:08 02/24/21	
Test Point ID:	PN2 LINE	Stop Time/Date:	13:02 02/24/21	
Test Gas:	Nitrogen	Test Duration:	53 minutes	
Test Flow:	4.3 SCFH	Average:	5.5	PPB
Technician:	JCH	Final:	5.5	PPB
		Specification:	20	PPB

Comments:
-----------