


Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Oxygen Test Report



Client:	TEST CLIENT	Analyzer:	Delta F	
Facility:	QAM HQ	Serial Number:	PT-11058-V6	
Tool / Equipment ID:		Calibration Due:	Not calibrated	
System:		Instrument Flow:	2.0	SCFH
Source ID:		Start Time/Date:	06:05 07/09/21	
Test Point ID:		Stop Time/Date:	06:59 07/11/21	
Test Gas:		Test Duration:	53 minutes	
Test Flow:	4.3 SCFH	Average:	17.1	PPB
Technician:		Final:	8.1	PPB
		Specification:	20	PPB


Comments: Removed zero and span settings



Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Moisture Test Report



Client:	TEST CLIENT		Analyzer:	Tracer 2	
Facility:	QAM HQ		Serial Number:	17481-44-1	
Tool / Equipment ID:			Calibration Due:	02/23/2023	
System:			Instrument Flow:	2.3	SCFH
Source ID:			Start Time/Date:	06:05 07/09/21	
Test Point ID:			Stop Time/Date:	06:59 07/11/21	
Test Gas:			Test Duration:	53 minutes	
Test Flow:	4.3	SCFH	Average:	1.8	PPB
Technician:			Final:	1.0	PPB
			Specification:	20	PPB

Comments: Removed zero and span settings