


Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Oxygen Test Report



| Client: | TEST CLIENT | | Analyzer: | Delta F | |
|----------------------|-------------|--|------------------|-------------|--------------------|
| Facility: | QAM HQ | | Serial Number: | PT-11058- | -V6 |
| Tool / Equipment ID: | | | Calibration Due: | Not calibra | ated |
| System: | | | Instrument Flow: | 2.0 | SCFH |
| Source ID: | | | Start Time/Date: | 16:34 07/1 | 4/21 |
| Test Point ID: | | | Stop Time/Date: | 07:42 07/1 | 5/21 |
| Test Gas: | | | Test Duration: | 15 hours 7 | minutes 43 seconds |
| Test Flow: | 4.3 SCFH | | Average: | 5.5 | PPB |
| Technician: | | | Final: | 1.1 | PPB |
| | | | Specification: | 20 | PPB |


Comments: Removed zero and span settings



Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Moisture Test Report



| Client: | TEST CLIENT | | Analyzer: | Tracer 2 | |
|----------------------|-------------|------|------------------|----------------|--------------------|
| Facility: | QAM HQ | | Serial Number: | 17481-44- | 1 |
| Tool / Equipment ID: | | | Calibration Due: | 02/23/2023 | |
| System: | | | Instrument Flow: | 2.3 | SCFH |
| Source ID: | | | Start Time/Date: | 16:34 07/14/21 | |
| Test Point ID: | | | Stop Time/Date: | 07:42 07/15/21 | |
| Test Gas: | | | Test Duration: | 15 hours 7 | minutes 43 seconds |
| Test Flow: | 4.3 | SCFH | Average: | 33.2 | PPB |
| Technician: | | | Final: | 25.3 | PPB |
| | | | Specification: | 20 | PPB |

Comments: Removed zero and span settings