


Comments:

Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Oxygen Test Report



Client:	TEST CLIENT		Analyzer:	Delta F	
Facility:	QAM HQ		Serial Number:	PT-11058-V6	
Tool / Equipment ID:			Calibration Due:	Not calibrated	
System:			Instrument Flow:	2.0	SCFH
Source ID:			Start Time/Date:	12:47 09/13/21	
Test Point ID:			Stop Time/Date:	12:49 09/13/21	
Test Gas:			Test Duration:	1 minutes	
Test Flow:	4.3	SCFH	Average:	4.2	PPB
Technician:			Final:	3.7	PPB
			Specification:	20	PPB




Comments:

Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Moisture Test Report



Client:	TEST CLIENT		Analyzer:	Tracer 2	
Facility:	QAM HQ		Serial Number:	17481-44-1	
Tool / Equipment ID:			Calibration Due:	02/23/2023	
System:			Instrument Flow:	2.3	SCFH
Source ID:			Start Time/Date:	12:47 09/13/21	
Test Point ID:			Stop Time/Date:	12:49 09/13/21	
Test Gas:			Test Duration:	1 minutes	
Test Flow:	4.3	SCFH	Average:	0.1	PPB
Technician:			Final:	0.1	PPB
			Specification:	20	PPB