


Comments:

Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Oxygen Test Report



Client:	TEST CLIENT		Analyzer:	Delta F	
Facility:	QAM HQ		Serial Number:	PT-26818-V6	
Tool / Equipment ID:			Calibration Due:	08/06/2022	
System:			Instrument Flow:	2.0	SCFH
Source ID:			Start Time/Date:	14:48 01/20/22	
Test Point ID:			Stop Time/Date:	14:48 01/20/22	
Test Gas:			Test Duration:	0 minutes	
Test Flow:	4.3	SCFH	Average:	2.9	PPB
Technician:			Final:	2.9	PPB
			Specification:	20	PPB




Comments:

Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Moisture Test Report



Client:	TEST CLIENT	Analyzer:	Tracer 2	
Facility:	QAM HQ	Serial Number:	17481-44-1	
Tool / Equipment ID:		Calibration Due:	02/23/2023	
System:		Instrument Flow:	2.3 SCFH	
Source ID:		Start Time/Date:	14:48 01/20/22	
Test Point ID:		Stop Time/Date:	14:48 01/20/22	
Test Gas:		Test Duration:	0 minutes	
Test Flow:	4.3 SCFH	Average:	26.4 PPB	
Technician:		Final:	26.4 PPB	
		Specification:	20 PPB	