


## **Quality Assurance Management, Inc.**

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

## **Oxygen Test Report**



			¬		
Client:	TEST CLIENT		Analyzer:	Delta F	
Facility:	QAM HQ		Serial Number:	PT-11058-V6	
Tool / Equipment ID:			Calibration Due:	08/06/2022	
System:			Instrument Flow:	2.0	SCFH
Source ID:			Start Time/Date:	12:59 09/13/21	
Test Point ID:			Stop Time/Date:	13:01 09/13/21	
Test Gas:			Test Duration:	2 minutes	
Test Flow:	4.3	SCFH	Average:	3.2	PPB
Technician:			Final:	3.4	PPB
			Specification:	20	PPB


Comments:
-----------



## **Quality Assurance Management, Inc.**

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

## **Moisture Test Report**



Client:	TEST CLIENT		Analyzer:	Tracer 2	
Facility:	QAM HQ		Serial Number:	17481-44-1	
Tool / Equipment ID:	D:		Calibration Due:	02/23/2023	
System:			Instrument Flow:	2.3	SCFH
Source ID:			Start Time/Date:	12:59 09/13/21	
Test Point ID:			Stop Time/Date:	13:01 09/13/21	
Test Gas:			Test Duration:	2 minutes	
Test Flow:	4.3	SCFH	Average:	0.1	PPB
Technician:			Final:	0.1	PPB
			Specification:	20	PPB

Comments:	