


## **Quality Assurance Management, Inc.**

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

## **Oxygen Test Report**



Client:	TEST CLIENT		Analyzer:	Delta F	
Facility:	QAM HQ		Serial Number:	PT-18690-V6	
Tool / Equipment ID:	TST123		Calibration Due:	7/2021	
System:	PN2		Instrument Flow:	2.0	SCFH
Source ID:	TST-SRC-ID		Start Time/Date:	13:15 02/26/21	
Test Point ID:	PN2 POC		Stop Time/Date:	14:02 02/26/21	
Test Gas:	Nitrogen		Test Duration:	46 minutes	
Test Flow:	4.3	SCFH	Average:	0.0	PPB
Technician:	JCH		Final:	0.0	PPB
			Specification:	20	PPB


Comments: OVERALL TEST OF COMPLETE FUNCTIONALITY



## **Quality Assurance Management, Inc.**

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

## **Moisture Test Report**



Client: TEST CLIENT Analyzer: Tracer 2 Serial Number: 17367-44-1 Facility: QAM HQ Tool / Equipment ID: TST123 Calibration Due: 8/2021 System: PN2 Instrument Flow: 2.3 **SCFH** Source ID: TST-SRC-ID Start Time/Date: 13:15 02/26/21 Test Point ID: PN2 POC Stop Time/Date: 14:02 02/26/21 Test Gas: Nitrogen Test Duration: 46 minutes Average: 28.6 Test Flow: 4.3 **SCFH PPB** Technician: JCH Final: 18.0 **PPB** Specification: 20 **PPB** 

Comments: OVERALL TEST OF COMPLETE FUNCTIONALITY