


Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Oxygen Test Report



Client:	TEST CLIENT	Analyzer:	Delta F	
Facility:	HQ	Serial Number:	PT-18690-V6	
Tool / Equipment ID:	TEST123	Calibration Due:	7/2021	
System:	PN2	Instrument Flow:	2.0	SCFH
Source ID:	TST-SRC	Start Time/Date:	04:44 02/25/21	
Test Point ID:	POC	Stop Time/Date:	07:31 02/25/21	
Test Gas:	Nitrogen	Test Duration:	2 hours 47 minutes	
Test Flow:	4.3 SCFH	Average:	0.1	PPB
Technician:	JCH	Final:	0.2	PPB
		Specification:	20	PPB


Comments:	Modified Test
-----------	---------------



Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Moisture Test Report



Client:	TEST CLIENT		Analyzer:	Tracer 2	
Facility:	HQ		Serial Number:	17367-44-1	
Tool / Equipment ID:	TEST123		Calibration Due:	8/2021	
System:	PN2		Instrument Flow:	2.3	SCFH
Source ID:	TST-SRC		Start Time/Date:	04:42 02/25/21	
Test Point ID:	POC		Stop Time/Date:	07:32 02/25/21	
Test Gas:	Nitrogen		Test Duration:	2 hours 49 minutes	
Test Flow:	4.3 SC	CFH	Average:	4.7	PPB
Technician:	JCH		Final:	4.6	PPB
			Specification:	20	PPB

Comments:	Modified Test
-----------	---------------