


Comments:

## **Quality Assurance Management, Inc.**

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

## **Oxygen Test Report**



Client:	TEST CLIENT		Analyzer:	Delta F					
Facility:	QAM HQ		Serial Number:	PT-23473-V6					
Tool / Equipment ID:			Calibration Due:	Not calibrated					
System:			Instrument Flow:	2.0	SCFH				
Source ID:			Start Time/Date:	17:31 06/23/21					
Test Point ID:			Stop Time/Date:	07:25 06/27/21					
Test Gas:			Test Duration:	13 hours 53 minutes		48 seconds			
Test Flow:	4.3	SCFH	Average:	0.1	PPB				
Technician:			Final:	-1.3	PPB				
			Specification:	20	PPB				




Comments:

## **Quality Assurance Management, Inc.**

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

## **Moisture Test Report**



Client:	TEST CLIENT		Analyzer:	Tracer 2				
Facility:	QAM HQ		Serial Number:	17481-44-	1			
Tool / Equipment ID:			Calibration Due:	02/23/202	3			
System:			Instrument Flow:	2.3	SCFH			
Source ID:			Start Time/Date:	17:31 06/2	23/21			
Test Point ID:			Stop Time/Date:	07:25 06/2	27/21			
Test Gas:			Test Duration:	13 hours 5	3 minutes 48 seconds			
Test Flow:	4.3	SCFH	Average:	2.2	PPB			
Technician:			Final:	1.8	PPB			
			Specification:	20	PPB			