


Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Oxygen Test Report



Client:	TEST CLIENT		Analyzer: Delta F		
Facility:	QAM HQ		Serial Number:	PT-18690-V6	
Tool / Equipment ID:	TEST123		Calibration Due:	7/2021	
System:	PN2		Instrument Flow:	2.0	SCFH
Source ID:	TST-SRC-ID		Start Time/Date:	15:14 02/26/21	
Test Point ID:	PN2 POC		Stop Time/Date:	07:08 03/01/21	
Test Gas:	Nitrogen		Test Duration:	15 hours 53 minutes	
Test Flow:	4.3	SCFH	Average:	0.0	PPB
Technician:	JCH		Final:	0.0	PPB
			Specification:	20	PPB


Comments: vveekend test	Comments:	Weekend test
-------------------------	-----------	--------------



Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Moisture Test Report



Client:	TEST CLIENT	
Facility:	QAM HQ	
Tool / Equipment ID:	TEST123	
System:	PN2	
Source ID:	TST-SRC-ID	
Test Point ID:	PN2 POC	
Test Gas:	Nitrogen	
Test Flow:	4.3	SCFH
Technician:	JCH	

Analyzer: Tracer 2

Serial Number: 17367-44-1

Calibration Due: 8/2021

Instrument Flow: 2.3 SCFH

Start Time/Date: 15:14 02/26/21

Stop Time/Date: 07:08 03/01/21

Test Duration: 15 hours 53 minutes

Average: 5.9 PPB

Final: 3.7 PPB
Specification: 20 PPB

Comments: Weekend test