


Comments:

Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Oxygen Test Report




Client:	TEST CLIENT	Analyzer:	Delta F	
Facility:	QAM HQ	Serial Number:	PT-18690-V6	
Tool / Equipment ID:	TEST BENCH	Calibration Due:	7/2021	
System:	PN2	Instrument Flow:	2.0 SCFH	
Source ID:	TST-SRC	Start Time/Date:	07:18 03/05/21	
Test Point ID:	TEST EQUIPMENT	Stop Time/Date:	08:21 03/05/21	
Test Gas:	Nitrogen	Test Duration:	1 hours 3 minutes	
Test Flow:	4.3 SCFH	Average:	4.0 PPB	
Technician:	JCH	Final:	4.0 PPB	
		Specification:	20 PPB	



Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Moisture Test Report



Client:	TEST CLIENT	Analyzer:	Tracer 2	
Facility:	QAM HQ	Serial Number:	17367-44-1	
Tool / Equipment ID:	TEST BENCH	Calibration Due:	8/2021	
System:	PN2	Instrument Flow:	2.3	SCFH
Source ID:	TST-SRC	Start Time/Date:	07:18 03/05/21	
Test Point ID:	TEST EQUIPMENT	Stop Time/Date:	08:21 03/05/21	
Test Gas:	Nitrogen	Test Duration:	1 hours 3 minutes	
Test Flow:	4.3 SCFH	Average:	6.1	PPB
Technician:	JCH	Final:	4.8	PPB
		Specification:	20	PPB

O	
Comments:	