


Comments:

Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Oxygen Test Report



Client:	TEST CLIENT		Analyzer:	Delta F	
Facility:	QAM HQ		Serial Number:	PT-18690-V6	
Tool / Equipment ID:			Calibration Due:	7/2021	
System:			Instrument Flow:	2.0	SCFH
Source ID:			Start Time/Date:	09:40 02/25/21	
Test Point ID:			Stop Time/Date:	09:41 02/25/21	
Test Gas:		Test		1 minutes 11 seconds	
Test Flow:	4.3	SCFH	Average:	0.1	PPB
Technician:			Final:	0.1	PPB
			Specification:	20	PPB




Comments:

Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Moisture Test Report



		1 .		
TEST CLIENT		Analyzer:	Tracer 2	
QAM HQ		Serial Number:	17367-44-1	
		Calibration Due:	8/2021	
		Instrument Flow:	2.3	SCFH
		Start Time/Date:	09:40 02/25/21	
		Stop Time/Date:	09:41 02/25/21	
		Test Duration:	1 minutes 11 second	
4.3	SCFH	Average:	4.8	PPB
		Final:	4.8	PPB
		Specification:	20	PPB
	TEST CLIENT QAM HQ 4.3	QAM HQ	QAM HQ Serial Number: Calibration Due: Instrument Flow: Start Time/Date: Stop Time/Date: Test Duration: 4.3 SCFH Average: Final:	QAM HQ Serial Number: 17367-44- Calibration Due: 8/2021 Instrument Flow: 2.3 Start Time/Date: 09:40 02/2 Stop Time/Date: 09:41 02/2 Test Duration: 1 minutes