


Comments:

Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Oxygen Test Report



Client:	TEXAS INSTRUMENTS		Analyzer:	Delta F	
Facility:	RFAB		Serial Number:	PT-18690-V6	
Tool / Equipment ID:			Calibration Due:	7/2021	
System:			Instrument Flow:	2.0	SCFH
Source ID:			Start Time/Date:	08:32 02/24/21	
Test Point ID:			Stop Time/Date:	08:32 02/24/21	
Test Gas:			Test Duration:	23 seconds	
Test Flow:	4.3	SCFH	Average:	0.0	PPB
Technician:			Final:	0.0	PPB
			Specification:	20	PPB




Comments:

Quality Assurance Management, Inc.

1620 Valwood Pkwy, Ste. 128 Carrollton, TX 75006 972-331-5800 QAM.com

Moisture Test Report



Client:	TEXAS INSTRUMENTS		Analyzer:	Tracer 2	
Facility:	RFAB		Serial Number:	17367-44-1	
Tool / Equipment ID:			Calibration Due:	8/2021	
System:			Instrument Flow:	2.3	SCFH
Source ID:			Start Time/Date:	08:32 02/24/21	
Test Point ID:			Stop Time/Date:	08:32 02/24/21	
Test Gas:			Test Duration:	23 seconds	
Test Flow:	4.3	SCFH	Average:	5.2	PPB
Technician:			Final:	5.2	PPB
			Specification:	20	PPB