SCOPE
Petroleum Services

WHEEL LOADER EQUIPMENT INSPECTION CHECK LIST

Annex to certificate N°: ST-4625-28

Date of inspection: 15/Nov/2025

	DESCRIPTION	CONDITION OR REMARKS
0	GENERAL DESCRIPTION OF THE EQUIPMENT	
0.0	Description: Wheel Loader Equipment	**WHEEL LOADER EQUIPMENT** **Manufacturer: SDLG** **MODEL: LG953** **REG NO: A 446 - MAYSAN** **CHASSIS NO: VLGL9530VP0622407**
1	SECTION	
1.1	Manufacturers operation manual	N/A
1.2	Operator competency certificate	OK
1.3	Hand Brake Interlock	OK
1.4	Hydraulic oil level	OK
1.5	Condition of oil	OK
1.6	System and hoses	OK
1.7	Lubrication	OK
1.8	Engine Indication	OK
1.9	Boom structure	OK
1.10	Control levers	OK
1.11	Track Roller frame	OK
1.12	Wear , damage , cracks , leaks	OK
1.13	Bucket	OK
1.14	Pins , Grease lines	OK
1.15	Tracks/ Tyres / Crawler	OK
1.16	Windows / Mirrors / Lights	OK
1.17	Undercarriage (including leaks)	OK
1.18	Belts / Hoses / Bolts	OK
1.19	Electrical System	OK
1.20	Power Train	OK
1.21	Power Unit	OK
1.22	Power Link	OK
1.23	Motion Alarm	OK
1.24	Counter Weight	OK
1.25	Main Frame	OK
1.26	Fire Extinguisher	OK
1.27	First Aid	OK

Scope petroleum services
SCOPE Petroleum Services
Lifting Department


Scope Petroleum Services
SCOPE Petroleum Services
Quality Control

Address: Burjesia-Tuba Area -After the Bridge Hamoud El-Wabdan
Contacts:operation@scopeps.com/sales@scopeps.com
Phone: +964 7803222202 / +964 7803773775

WHEEL LOADER EQUIPMENT INSPECTION CHECK LIST


Annex to certificate N°: ST-4625-28 Date of inspection: 15/Nov/2025

Comment:










Surveyor's Name: Mohamed Abdel Halim

Signature:

Scope Petroleum Services Quality Control

Scope petroleum services Lifting Department

Address: Burjesia-Tuba Area -After the Bridge Hamoud El-Wabdan
Contacts:operation@scopeps.com/sales@scopeps.com
Phone: +964 7803222202 / +964 7803773775

SCOPE
Petroleum Services

Certificate of Thorough Examination & NDE for Hydraulic Wheel Loader

Date of Through Examination: 15/Nov/2025			Certificate number: ST-4625-28
Name and Address of employer for whom the thorough examination was made: MSK Co., BASRA , IRAQ			Address of premises at which the examination was made: MSK YARD
Identification NO	QTY	Description	Date of next examination
VLGL9530VP0622407	1	WHEEL LOADER EQUIPMENT MANUFACTURER: SDLG MODEL: LG953 REG NO: A 446 - MAYSAN CHASSIS NO: VLGL9530VP0622407 BUCKET S/N: 08 EXAMINED IN ACCORDING TO BS EN 474-5:2006+A3:2013	14/Nov/2026

Tools Details

Tools Details	Measuring Tape S/N: SCP-L-001	Vernier Calliper S/N: SCP-L-002

NDT Details

Standard: BS EN ISO 9934-1	Equipment type: YOKE S\N: 3291K	Contrast Media: WHITE
Procedure: SPS-IMS-P027	Method: WET	Indicator: MAG INK

Result	MPI was carried out on the critical stress areas of bucket were found free from any surface defects

Is this the first examination after installa or assembly at a new site or location?	YES		NO	√	Was the examination carried out: Within an interval of 6 months?	YES		NO	√
					Within an interval of 12 months?	YES	√	NO	
If the answer to the above question is YE has the equipment been installed correct	YES		NO		In accordance with an examinatio scheme?	YES	√	NO	
					After the occurrence of exceptiona circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the def

Particulars of any repair, renewal or alteration required to remedy the defect identified above: (NONE)

Particulars of any tests carried out as part of the examination: (Visual , Function , Performance , MPI Tests)

Is This Equipment Safe To Operate?	YES	√	NO	

Name of person making this report: Mohamed Abdel Halim Signature:	Name of person authenticating this report: Mostafa Shama

Name of employer of persons making and authenticating this report:
Scope petroleum services: lifting@scopeps.com

Scope petroleum services Lifting Department SCOPE Petroleum Services

Scope Petroleum Services SCOPE Petroleum Services Quality Control