Brandon Avalos

Hume Vertical Studio
SCI-Arc FA26
Midterm Review, October 19, 2026

ARROYO SECO STABLES, SOUTH PASADENA

“After the revolution, who’s going to pick up the garbage on Monday morning?”

MIERLE LADERMAN UKELES, MANIFESTO FOR MAINTENANCE ART, 1969

SITE PLAN / NORTH UP

Arroyo Seco Stables, South Pasadena. Lower Arroyo, downstream of Devil’s Gate Dam.





Maintenance that is hidden gets abandoned. A sediment node makes it public, permanent, and productive.

PROBLEM

Fire-loosened sediment from the San Gabriels is trapped at Devil's Gate Dam, removed each year, and trucked away as waste out of public view.

PROPOSAL

A public station where the river's maintenance becomes visible, paid work, and that work rebuilds the land, the river, and the people who do it.

SEDIMENT > SOIL > PLANTS > SLOPES > LESS SEDIMENT



JOINT / 06-07

1" = 1'-0"



SLIVER / 08-09

1/4" = 1'-0"



BUILDING / 10

1/16" = 1'-0"



SITE / 03, 11

1/32" = 1'-0"



SECTION DETAIL SCALE 1" = 1'-0" HUME

SECTION DETAIL

1" = 1'-0"

The floor is a lashed sandwich: CLT plate, compressed cork, and tile hung below, bound at the bullnose edge by a Dyneema strap the crew can reach and retension.

FLOOR PLATE / TOP TO BOTTOM



The floor is made of what the node processes. The Dyneema creeps, the earth layer sags, and the crew retensions it: maintenance performed in public view.

WALL / OUTSIDE TO INSIDE



Two thin skins held apart act like an I-beam: stiffness from depth, not mass. The cork core gives continuous insulation and acoustic damping.

EXPLODED IN SECTION / HATCHED BY MATERIAL



SLIVER DRAWING

NOT TO SCALE

One sliver holds the whole loop: sediment is hoisted in, worked into soil, and grown into plants, with the crew visible on every floor.

SLIVER RENDER

PERSPECTIVE FROM THE RIVER PATH

From the river path, the sliver rises beside the bridge on a single red mast, and the veil turns the work on each floor into silhouette.

BUILDING SECTION

1/16" = 1'-0"



Set against the bridge’s arches, one sliver stands on the bank on a single footing, leaving the channel and the riverbed clear.

OVERALL SECTION / SITE CONDITION

1/32" = 1'-0"



The three masses hang over the channel beneath the bridge, putting the river's upkeep in view of the road, the path, and the bridge.



02 / FLOOR PLATES + MAST



03 / MAST + VEIL

MODEL PHOTOGRAPHS / 01 WALLS + VEIL

THREE VIEWS

Ply walls, layered floor plates, and a clear printed veil: the model tests how the work reads as silhouette through the skin.