DI2AZ-02

CIRCUIT INSPECTION


DTC	B1211 / 11	Driver door ECU communication stop
-----	------------	------------------------------------

CIRCUIT DESCRIPTION

This DTC is output when communication stops between driver door ECU and body No.1 ECU.

DTC No.	DTC Detecting Condition	Trouble Area
B1211/11	No communication from driver door ECU more than 10 se-	Driver door ECU
	conds.	Wireharness

WIRING DIAGRAM



INSPECTION PROCEDURE

1

Check driver door ECU.

CHECK:

Check if the driver door window glass auto up.

HINT:


With this inspection, the driver door ECU CPU can be diagnosed if it works normally or not.

NG

Replace the driver ECU.

OK

2 Check wireharness.



PREPARATION:

Disconnect connector of body No.2 ECU, "D24" of driver door ECU and "D12" of rear left ECU.

CHECK:

- (a) Check continuity between terminals MPX1 of body No.2 ECU and MPX1 of driver door ECU.
- (b) Check continuity between terminals MPX2 of driver door ECU and MPX1 of rear left door ECU.

OK:

There is a continuity in wireharness of both (a) and (b). or either (a) or (b).

HINT:

If there is OPEN in wireharness of either (a) or (b), please repair it.

NG

Repair or replace wireharness.

ОК

Replace the driver door ECU.