
DI26L-03

ACC Power Source Circuit

CIRCUIT DESCRIPTION


This is the power source for A/C control assembly and servomotors, etc.

WIRING DIAGRAM



INSPECTION PROCEDURE

1 Check voltage between terminals ACC and GND of A/C control assembly connector.



PREPARATION:

Remove A/C control assembly with connectors still connected. **CHECK:**

- (a) Turn ignition switch ON.
- (b) Measure voltage between terminals ACC and GND of A/C control assembly.

OK:

Voltage: Battery positive voltage




Proceed to next circuit inspection shown on problem symptoms table (See page DI-930).

NG

2

Check continuity between terminal GND of A/C control assembly and body ground.



CHECK:

Measure resistance between terminal GND of A/C control assembly and body ground.

OK:


Resistance : 0 Ω (continuity)

NG

Repair or replace harness or connector.

ОК

3 Check RADIO No.2 fuse.



PREPARATION:

Remove RADIO No.2 fuse from driver side J/B.

CHECK:

Check continuity of RADIO No.2.

<u>OK:</u>

Continuity



Check for short in all the harness and components connected to the RADIO No.2 fuse (See attached wiring diagram).



Check and repair harness and connector between A/C control assembly and battery.